



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Marvulli INC	Type of Inspection:	Framing Inspection
Project	22-240 Hilton Garden Inn	Date of Inspection	July 22, 2024
Inspector Name	Michael Tolhurst	Time of Inspection	07:32 AM

NOTES

14 Items Inspected	12 Satisfactory	0 Unsatisfactory	2 N/A
-----------------------	--------------------	---------------------	----------

INSPECTION ITEMS

General

Are air compressors and generators set up safely?	N/A
Are nail guns being used safely?	N/A
Are hole and wall openings protected per OSHA regulations?	Satisfactory
Are stairways in place as required?	Satisfactory
If personal fall restraint / arrest systems are being used, are the anchors and lanyards set up correctly?	Satisfactory
is emergency equipment, including first aid kits and fire extinguishers available?	Satisfactory
Are emergency and labor law postings in place?	Satisfactory
Is scaffolding set up correctly and being used safely?	Satisfactory
Is fall protection in place where required?	Satisfactory

Is all required PPE being worn including hard hats and eye protection?

Satisfactory

Are electrical cords and other electrical related items in safe condition?

Satisfactory

Are hand and power tools being used safely?

Satisfactory

Is the company safety manual on site?

Satisfactory

Are SDS on site and available to employees?

Satisfactory