

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

| Company | Marvulli INC | Type of Inspection: | Framing Inspection |
|----------------|--------------------------|-----------------------|--------------------|
| Project | 22-240 Hilton Garden Inn | Date of Inspection | July 26, 2024 |
| Inspector Name | Michael Tolhurst | Time of Inspection | 07:34 AM |

| NOTES | | | | | | |
|-----------------|--------------|----------------|-----|--|--|--|
| 14 | 14 | 0 | 0 | | | |
| Items Inspected | Satisfactory | Unsatisfactory | N/A | | | |

INSPECTION ITEMS

| General | |
|--|--------------|
| Are air compressors and generators set up safely? | Satisfactory |
| Are nail guns being used safely? | Satisfactory |
| Are hole and wall openings protected per OSHA regulations? | Satisfactory |
| Are stairways in place as required? | Satisfactory |
| If personal fall restraint / arrest systems are being used, are the anchors and lanyards set up correctly? | Satisfactory |
| is emergency equipment, including first aid kits and fire extinguishers available? | Satisfactory |
| Are emergency and labor law postings in place? | Satisfactory |
| Is scaffolding set up correctly and being used safely? | Satisfactory |
| Is fall protection in place where required? | Satisfactory |

| Is all required PPE being worn including hard hats and eye protection? | Satisfactory |
|--|--------------|
| Are electrical cords and other electrical related items in safe condition? | Satisfactory |
| Are hand and power tools being used safely? | Satisfactory |
| Is the company safety manual on site? | Satisfactory |
| Are SDS on site and available to employees? | Satisfactory |