



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Marvulli INC	Type of Inspection:	Framing Inspection
Project	22-240 Hilton Garden Inn	Date of Inspection	August 06, 2024
Inspector Name	Michael Tolhurst	Time of Inspection	01:38 PM

NOTES

14 Items Inspected	14 Satisfactory	0 Unsatisfactory	0 N/A
-----------------------	--------------------	---------------------	----------

INSPECTION ITEMS

General

Are air compressors and generators set up safely? **Satisfactory**

Are nail guns being used safely? **Satisfactory**

Are hole and wall openings protected per OSHA regulations? **Satisfactory**

Are stairways in place as required? **Satisfactory**

If personal fall restraint / arrest systems are being used, are the anchors and lanyards set up correctly? **Satisfactory**

is emergency equipment, including first aid kits and fire extinguishers available? **Satisfactory**

Are emergency and labor law postings in place? **Satisfactory**

Is scaffolding set up correctly and being used safely? **Satisfactory**

Is fall protection in place where required? **Satisfactory**

Is all required PPE being worn including hard hats and eye protection?

Satisfactory

Are electrical cords and other electrical related items in safe condition?

Satisfactory

Are hand and power tools being used safely?

Satisfactory

Is the company safety manual on site?

Satisfactory

Are SDS on site and available to employees?

Satisfactory