



# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Marvulli INC	<b>Type of Inspection:</b>	Framing Inspection
<b>Project</b>	22-240 Hilton Garden Inn	<b>Date of Inspection</b>	August 09, 2024
<b>Inspector Name</b>	Michael Tolhurst	<b>Time of Inspection</b>	06:59 AM

## NOTES

14 Items Inspected	14 Satisfactory	0 Unsatisfactory	0 N/A
-----------------------	--------------------	---------------------	----------

## INSPECTION ITEMS

General	
Are air compressors and generators set up safely?	Satisfactory
Are nail guns being used safely?	Satisfactory
Are hole and wall openings protected per OSHA regulations?	Satisfactory
Are stairways in place as required?	Satisfactory
If personal fall restraint / arrest systems are being used, are the anchors and lanyards set up correctly?	Satisfactory
is emergency equipment, including first aid kits and fire extinguishers available?	Satisfactory
Are emergency and labor law postings in place?	Satisfactory
Is scaffolding set up correctly and being used safely?	Satisfactory
Is fall protection in place where required?	Satisfactory

**Is all required PPE being worn including hard hats and eye protection?**

**Satisfactory**

**Are electrical cords and other electrical related items in safe condition?**

**Satisfactory**

**Are hand and power tools being used safely?**

**Satisfactory**

**Is the company safety manual on site?**

**Satisfactory**

**Are SDS on site and available to employees?**

**Satisfactory**