

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Marvulli INC	Type of Inspection:	General Constructi	ion	
Project	Reedley Col	Date of Inspection	November 14, 202	4	
Inspector Name	Dominic Jones	Time of Inspection	03:57 PM		
NOTES					
lte	19 ems Inspected	12 Satisfactory	0 Unsatisfactory	7 N/A	
INSPECTION ITEMS					
General					
Is emergency extinguisher(Satisfactory				
Is safety doc Meetings)	Satisfactory				
Is drinking water and shade set up sufficient for the amount of workers?				Satisfactory	
Are emergency and labor law postings in place?				Satisfactory	
Is Personal Protective Equipment being worn as required?				Satisfactory	
Are scaffolding safety procedures being followed?				N/A	

Satisfactory

Satisfactory

N/A

Are hand and power tools being used safely?

Is good housekeeping being maintained?

Is fall protection in place where required?

Is trenching & excavation work being done safely?	N/A
Are confined space safety procedures being followed?	N/A
Are scissor lifts / elevated platforms being used safely?	N/A
Are boom lifts and other aerial devices being used safely?	N/A
Is heavy equipment being used safely?	Satisfactory
Are electrical items being used safely?	Satisfactory
Are roofing operations being performed safely?	Satisfactory
Is demolition work being done safely?	N/A
Are all other tasks being performed safely?	Satisfactory
Any other items?	Satisfactory