

SAFETY INSPECTION REPORT

CONDUCTED FOR:
Miller Construction

PROJECT:
Workman Highschool



INSPECTION TYPE:
General Construction

INSPECTOR : CHUCK HIPPENSTIEL
DATE : SEPTEMBER 19, 2024
CITY : CITY OF INDUSTRY
STATE : CALIFORNIA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53
Items Inspected

28
Satisfactory

1
Unsatisfactory

24
N/A

I am at Freddy at workman high school just starting out the project has over the existing field and tennis courts. All electrical has been identified in as marked as there's underground bolts running across the job site. No pipes were found with asbestos at this point. Fred had a good understanding site Safety the only thing he needs to add is a trailer is a map of the closest hospital. He did have the numbers listed, however, talk about going forward. Heavy equipment is running more. Make sure all guys are wearing safety vest. Fred was very proactive and said he was glad that I came by. Was welcome to come by. At any time. Our conversation was helpful.

INSPECTION ITEMS

Documentation

Site Contact

Satisfactory

Comment


Freddy was a superintendent return Inspector with Chuck Hippenstiel 909-557-4108

Safety Program (Including IIPP)

Satisfactory

Comment


Safety Program is available



Heat Illness Prevention Program

Satisfactory

Comment

<p>Let me know who you want to replace the heat name with this Mando needs to be updated. Still has Hunter in there.</p>	
--------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------

<p>Safety Data Sheets</p>	<p>Satisfactory</p>
----------------------------------	----------------------------

<p>Daily Inspections</p>	<p>Satisfactory</p>
---------------------------------	----------------------------

Comment	
<p>Daily inspections need to be conducted.</p>	<p>-</p>


<p>Tailgate Meetings</p>	<p>Satisfactory</p>
---------------------------------	----------------------------

Comment	
<p>Tailgate meetings are required to be done at least every 10 working days.</p>	<p>-</p>

<p>Sub-Contractor Meetings</p>	<p>Satisfactory</p>
---------------------------------------	----------------------------

<p>OSHA Permits</p>	<p>N/A</p>
----------------------------	-------------------

<p>Labor Law Postings</p>	<p>Satisfactory</p>
----------------------------------	----------------------------

Comment	
<p>Labor law postings are in place as required.</p>	

<p>Emergency / Other Postings</p>	<p>Satisfactory</p>
------------------------------------------	----------------------------

Comment

Emergency and medical clinic locations are required to be posted

-

First Aid / CPR Certification

Satisfactory

Comment

Current

-

Emergency Items

Access / Egress

Satisfactory

Comment

Availability of emergency medical service for workers on site



Elevator for Hoisting Workers (if needed)

N/A

Fire Extinguisher(s)

Unsatisfactory

Comment


Good till August 2025



First Aid Kit(s)

Satisfactory

Comment

First aid it was on site	
--------------------------	-------------------------------------------------------------------------------------


Eye Wash Station	Satisfactory
------------------	--------------

Other Fire Fighting Equipment (If needed)	N/A
-------------------------------------------	-----

General Items

Restrooms	Satisfactory
-----------	--------------

Comment


Restroom and hand wash provided by General contractor	
-------------------------------------------------------	--------------------------------------------------------------------------------------

Hand Washing Stations	Satisfactory
-----------------------	--------------

Waste Containers	Satisfactory
------------------	--------------

Potable Water	Satisfactory
---------------	--------------

Comment

Had water on site	
-------------------	-------------------------------------------------------------------------------------

Shade	Satisfactory
--------------	---------------------

Tools & Equipment

Power Tools	Satisfactory
--------------------	---------------------

Comment

Power and hand tools were in good shape	
-----------------------------------------	--------------------------------------------------------------------------------------

Hand Tools	Satisfactory
-------------------	---------------------

Powder Actuated Tools	N/A
------------------------------	------------

Pneumatic Nailers	N/A
--------------------------	------------

Mobile Elevated Work Plarforms (MEWP's)	N/A
------------------------------------------------	------------

Powered Industrial Trucks	N/A
----------------------------------	------------

Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
----------------------------------------------------------	------------

Cranes	N/A
---------------	------------

Cylinder Storage	Satisfactory
-------------------------	---------------------

Ladders	N/A
----------------	------------

Operations

Personal Protective Equipment	Satisfactory
--------------------------------------	---------------------

Comment	
All PPE being worn	-

Trenching & Excavation	N/A
-----------------------------------	------------

Fall Protection	N/A
------------------------	------------

Guardrails	N/A
-------------------	------------

Floor / Wall Openings	N/A
------------------------------	------------

Supported Scaffolding	N/A
------------------------------	------------

Mobile Scaffolding	N/A
---------------------------	------------

Suspended Scaffolding	N/A
------------------------------	------------

Confined Spaces	N/A
------------------------	------------


Impalement Hazards	Satisfactory
---------------------------	---------------------

Traffic Control	Satisfactory
------------------------	---------------------

Roofing Operations	N/A
---------------------------	------------

Housekeeping	Satisfactory
---------------------	---------------------

Comment	
----------------	--

Housekeeping in good shape.	
-----------------------------	-------------------------------------------------------------------------------------


Demolition	Satisfactory
-------------------	---------------------

Silica Control	N/A
-----------------------	------------

Rigging Operations	N/A
---------------------------	------------

Hot Work	N/A
-----------------	------------

Electrical Safety	Satisfactory
--------------------------	---------------------

Comment	
Electrical has been identified	

Lockout / Tagout	N/A
-------------------------	------------

Stairways, Ramps, Runways	Satisfactory
----------------------------------	---------------------

Comment	
Stairs are barricaded for no use at time of inspection	-

Other Items (that were observed)	N/A
-----------------------------------------	------------