

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Pacific Hydrotech Corporation	Type of Inspection:	General Construction
Project	C2213 Belle Terre French Valley	Date of Inspection	June 04, 2024
Inspector Name	Frank Gomez	Time of Inspection	10:54 AM

NOTES			
19	11	0	8
Items Inspected	Satisfactory	Unsatisfactory	N/A

INSPECTION ITEMS

General	
Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	Satisfactory
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	Satisfactory

Is drinking water and shade set up sufficient for the amount of workers? Satisfact		
Comment		
Yes	-	
Yes plenty of water		

Are emergency and labor law postings in place?

Is fall protection in place where required?	N/A
Is trenching & excavation work being done safely?	N/A
Are confined space safety procedures being followed?	N/A
Are scissor lifts / elevated platforms being used safely?	N/A
Are boom lifts and other aerial devices being used safely?	N/A
Is heavy equipment being used safely?	Satisfactory
Are electrical items being used safely?	Satisfactory
Comment	
Big Bear Electric on site	

Is good housekeeping being maintained?

Comment

Yes

Are hand and power tools being used safely?

Are scaffolding safety procedures being followed?

Is Personal Protective Equipment being worn as required?

Satisfactory

Satisfactory

Satisfactory

N/A

Are	roofina	operations	beina	performed	safelv?
/		oporationo	Some	pononioa	callery i

Is demolition work being done safely?

Are all other tasks being performed safely?

Comment

Dry packing



Any other items?	Satisfactory
Comment	
Tighten bolts	

N/A

Satisfactory