

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company Project	Pacific Hydrotech Corporation	Type of						
Project		Inspection:	General Construction	n				
	C2213 Belle Terre French Valley	Date of Inspection	July 02, 2024					
Inspector Name	Frank Gomez	Time of Inspection	01:05 PM					
NOTES								
lte	19 ems Inspected	14 Satisfactory	0 Unsatisfactory	5 N/A				
	INSPECTION ITEMS							
General								
Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? Satisfactory								
Comment								
	Comment							
Type your cus	tom comment							

Is drinking water and shade set up sufficient for the amount of workers? Satisfactory
Comment

Res 1

Are emergency and labor law postings in place?	Satisfactory
Is Personal Protective Equipment being worn as required?	Satisfactory
Are scaffolding safety procedures being followed?	N/A
Are hand and power tools being used safely?	Satisfactory
Comment	
Yes	

Is good housekeeping being maintained?	Satisfactory
Comment	
Yes	
Is fall protection in place where required?	Satisfactory

Is trenching & excavation work being done safely?

Satisfactory

Are confined space safety procedures being followed?	Satisfactory
Are scissor lifts / elevated platforms being used safely?	N/A
Are boom lifts and other aerial devices being used safely?	N/A
Is heavy equipment being used safely?	Satisfactory
Are electrical items being used safely?	Satisfactory
Comment	

Big Bear Electric



Are roofing operations being performed safely? N/A Is demolition work being done safely? N/A Are all other tasks being performed safely? Satisfactory Comment Satisfactory Big Bear and PH on site Image: Satisfactory

Any other items?

Satisfactory