

# **PROJECT INSPECTION**

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company Pacific Hydro	tech Corporation Type of Inspection	on: General Construction
Project C2220 Plant	128 Reservoir PS Date of Inspection	December 05, 2024
Inspector Name Janell Gomez	Time of Inspection	12:28 PM

NOTES				
19	12	0	7	
Items Inspected	Satisfactory	Unsatisfactory	N/A	

## **INSPECTION ITEMS**

INSPECTION ITEMS	
General	
Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	Satisfactory
Comment	
Yes available on-site -	
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	Satisfactory
Comment	
Yes available on-site -	
Is drinking water and shade set up sufficient for the amount of workers?	

Comment	
Yes available on-site	-
Is drinking water and shade set up sufficient for the amount of v	workers? Satisfactory
Comment	
Adequate water on-site	

## Are emergency and labor law postings in place?

**Satisfactory** 

#### Comment

Yes labor laws and permits onsite



## Is Personal Protective Equipment being worn as required?

**Satisfactory** 

#### Comment

Yes proper PPE being worn



## Are scaffolding safety procedures being followed?

N/A

## Are hand and power tools being used safely?

Satisfactory

## Is good housekeeping being maintained?

**Satisfactory** 

#### Comment

Housekeeping maintained



Is fall protection in place where required?

N/A

s trenching & excavation work being done safely?	Satisfactory
Comment	
Yes	
Are confined space safety procedures being followed?	N/A
Are scissor lifts / elevated platforms being used safely?	N/A
Are boom lifts and other aerial devices being used safely?	N/A
ls heavy equipment being used safely?	Satisfactory
Comment	
Yes, heavy machinery being used safely	
Are electrical items being used safely?	Satisfactory
Comment	
Yes electrical items being used safely	-
Are roofing operations being performed safely?	N/A
s demolition work being done safely?	N/A
Are all other tasks being performed safely?	N/A Satisfactory