



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Pacific Hydrotech Corporation	Type of Inspection:	General Construction
Project	C2223 Irvine DeSalter	Date of Inspection	August 05, 2024
Inspector Name	Ricardo Vanzzini	Time of Inspection	12:44 PM

NOTES

19 Items Inspected	10 Satisfactory	0 Unsatisfactory	9 N/A
------------------------------	---------------------------	----------------------------	-----------------

Work on site consists of continued electrical wiring installation and pipe replacement.

INSPECTION ITEMS

General

Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? **Satisfactory**

Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings) **Satisfactory**

Is drinking water and shade set up sufficient for the amount of workers? **Satisfactory**

Are emergency and labor law postings in place? **Satisfactory**

Is Personal Protective Equipment being worn as required? **Satisfactory**

Are scaffolding safety procedures being followed? **N/A**

Are hand and power tools being used safely? **Satisfactory**

Is good housekeeping being maintained? **Satisfactory**

Comment

Good housekeeping is being maintained throughout the site.



Is fall protection in place where required?

N/A

Is trenching & excavation work being done safely?

N/A

Are confined space safety procedures being followed?

N/A

Are scissor lifts / elevated platforms being used safely?

N/A

Are boom lifts and other aerial devices being used safely?

N/A

Is heavy equipment being used safely?

N/A

Are electrical items being used safely?

Satisfactory

Are roofing operations being performed safely?

N/A

Is demolition work being done safely?


N/A

Are all other tasks being performed safely?

Satisfactory

Comment

Pictured is the pipe parts that are being replaced safely.



Any other items?

Satisfactory