

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Pacific Hydrotech Corporation	Type of Inspection:	General Construction
Project	C2232 Deane PS Santa Clarita	Date of Inspection	December 17, 2024
Inspector Name	Janell Gomez	Time of Inspection	08:17 AM

NOTES			
19	10	0	9
Items Inspected	Satisfactory	Unsatisfactory	N/A

PH crew Installing pipe supports and dry packing .

INSPECTION ITEMS

General		
Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? Sat		
Comment		
Yes on-site		

Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	Satisfactory
Comment	
He available onsite -	

Is drinking water and shade set up sufficient for the amount of workers?	Satisfactory
Comment	
Yes plenty of water on-site	-
Are emergency and labor law postings in place?	Satisfactory
Comment	
Yes labor laws are posted	-
Is Personal Protective Equipment being worn as required?	Satisfactory

Comment	
Yes proper PPE being used	

Are scaffolding safety procedures being followed?	N/A
Are hand and never tools hains used astaly?	Setiefectory
Are hand and power tools being used safely?	Satisfactory
Comment	
Yes hand tools being used safely	-
Is good housekeeping being maintained?	Satisfactory
Comment	
Yes housekeeping is maintained	-
Is fall protection in place where required?	N/A
Is trenching & excavation work being done safely?	N/A
	N1/A
Are confined space safety procedures being followed?	N/A

Are scissor lifts / elevated platforms being used safely?	N/A
---	-----

Are boom lifts and other aerial devices being used safely?	N/A
Is heavy equipment being used safely?	N/A
Are electrical items being used safely?	Satisfactory
Comment	
Yes electrical tools being used safely	-
Are roofing operations being performed safely?	N/A
Is demolition work being done safely?	N/A
Are all other tasks being performed safely?	Satisfactory
Comment	
PH crew is working safely	-
Any other items?	Satisfactory