



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Pacific Hydrotech Corporation	Type of Inspection:	General Construction
Project	C2301 La Water Wheel	Date of Inspection	July 29, 2024
Inspector Name	Frank Gomez	Time of Inspection	02:07 PM

NOTES

19 Items Inspected	11 Satisfactory	0 Unsatisfactory	8 N/A
-----------------------	--------------------	---------------------	----------

INSPECTION ITEMS

General	
Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	Satisfactory
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	Satisfactory
Is drinking water and shade set up sufficient for the amount of workers?	Satisfactory
Are emergency and labor law postings in place?	Satisfactory
Is Personal Protective Equipment being worn as required?	Satisfactory
Are scaffolding safety procedures being followed?	N/A
Are hand and power tools being used safely?	Satisfactory
Is good housekeeping being maintained?	Satisfactory
Comment	

Good housekeeping.
But need to get trash bin dumped



Is fall protection in place where required?

Satisfactory

Is trenching & excavation work being done safely?

N/A

Are confined space safety procedures being followed?

N/A

Are scissor lifts / elevated platforms being used safely?

N/A

Are boom lifts and other aerial devices being used safely?

N/A

Is heavy equipment being used safely?

Satisfactory

Comment

No one on site
However Manpower has crew on site?



Are electrical items being used safely?

N/A

Are roofing operations being performed safely?

N/A

Is demolition work being done safely?

N/A

Are all other tasks being performed safely?

Satisfactory

Comment

Rental equipment still on site



Any other items?

Satisfactory

Comment

Reporting for replacement of bin

