



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Pacific Hydrotech Corporation	Type of Inspection:	General Construction
Project	C2301 La Water Wheel	Date of Inspection	December 17, 2024
Inspector Name	Janell Gomez	Time of Inspection	12:12 PM

NOTES

19 Items Inspected	9 Satisfactory	0 Unsatisfactory	10 N/A
------------------------------	--------------------------	----------------------------	------------------

PH crew NOT on site at the moment but landscapers are onsite

INSPECTION ITEMS

General

Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	Satisfactory
Comment	
Yes on-site	-

Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	Satisfactory
Comment	
Yes on-site	-

Is drinking water and shade set up sufficient for the amount of workers?	Satisfactory
Comment	
Yes available on-site	-

Are emergency and labor law postings in place?	Satisfactory
Comment	

Yes posted on-site

-

Is Personal Protective Equipment being worn as required?

Satisfactory

Are scaffolding safety procedures being followed?

N/A

Are hand and power tools being used safely?

Satisfactory

Is good housekeeping being maintained?

Satisfactory

Comment

Yes housekeeping is maintained



Is fall protection in place where required?

N/A

Is trenching & excavation work being done safely?

N/A

Are confined space safety procedures being followed?

N/A

Are scissor lifts / elevated platforms being used safely?

N/A

Are boom lifts and other aerial devices being used safely?

N/A

Is heavy equipment being used safely?

N/A

Are electrical items being used safely?

N/A

Are roofing operations being performed safely?

N/A

Is demolition work being done safely?

N/A

Are all other tasks being performed safely?

Satisfactory

Comment	
Yes, landscapers working safely on-site	-

Any other items?	Satisfactory
-------------------------	---------------------