

EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Pacific Hydrotech Corporation	Type of Inspection:	Crane				
Project	C2302 EMWD SJVRWRF	Date of Inspection	October 16, 2024				
Inspector Name	Chuck Erickson	Time of Inspection	06:39 AM				
		NOTES					
		NOTES					
lte	46 ems Inspected	45 Satisfactory	0 Unsatisfactory	1 N/A			
INSPECTION ITEMS							
General							
Click "Satisfa	Satisfactory						
	Comment						
Link belt j9k54							
Click "Satisfa	Satisfactory						
	Comment						
70 ton			-				
Click "Satisfactory" and enter the crane capacity Sati							
	Comment						
90,500			-				
Click "Satisfactory" and enter the oiler's name N/A							
Jiidi. Juliale	and officer the officer of fluid			IVA			
Safety Guard	s and Plates/Latches			Satisfactory			
Carrier frame	, rotate base			Satisfactory			

General Hardware	Satisfactory
Wire Rope	Satisfactory
Reeving	Satisfactory
Block	Satisfactory
Crane stability	Satisfactory
Hook	Satisfactory
Sheeves	Satisfactory
Boom/Jib	Satisfactory
Gantry, Pendants, Boom Stops	Satisfactory
Walks, ladders, handrails	Satisfactory
Wind locks, chocks, stops	Satisfactory
Tires, Wheels, Tracks	Satisfactory
Leaks-fuel, lube, oil, water	Satisfactory
Radius indicator	Satisfactory
Outriggers/Locking Device	Satisfactory
Area Safety	Satisfactory
Unusual noises	Satisfactory
Control Action	Satisfactory
Brakes/boom/load/rotate	Satisfactory

No load test	Satisfactory
Fleeting sheeve	Satisfactory
Limit switches	Satisfactory
Gauges	Satisfactory
Control/Brakes	Satisfactory
Visibility	Satisfactory
Load Rating Charts	Satisfactory
Safety devices	Satisfactory
Emergency stops	Satisfactory
List/trim indicators	Satisfactory
Boom Angle/Radius Indicator	Satisfactory
Housekeeping	Satisfactory
Engine/compressor	Satisfactory
Lubrication	Satisfactory
Battery	Satisfactory
Lights	Satisfactory
Glass	Satisfactory
Clutch/Brake Linings	Satisfactory
Electric motors	Satisfactory

Warning tags	Satisfactory
Fire Extinguisher	Satisfactory