

### PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

 Company
 Pacific Hydrotech Corporation
 Type of Inspection:
 General Construction

 Project
 C2304 2401 N. Bristol
 Date of Inspection
 July 24, 2024

 Inspector Name
 Frank Gomez
 Time of Inspection
 10:20 AM

**NOTES** 

19

Items Inspected

14 Satisfactory **0** Unsatisfactory **5** N/A

# **INSPECTION ITEMS**

#### General

Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?

**Satisfactory** 

Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)

Satisfactory

Is drinking water and shade set up sufficient for the amount of workers?

Satisfactory

Comment

Cold water



Are emergency and labor law postings in place?

**Satisfactory** 

Comment

Update trenching permit



# Is Personal Protective Equipment being worn as required? Comment Type your custom comment... -

#### Are scaffolding safety procedures being followed?

#### **Satisfactory**

#### Comment

Type your custom comment...



#### Are hand and power tools being used safely?

#### Satisfactory

#### Comment

Type your custom comment...



#### Is good housekeeping being maintained?

#### Satisfactory

#### Comment



Is fall protection in place where required?

Satisfactory

Is trenching & excavation work being done safely?

Satisfactory

Are confined space safety procedures being followed?

N/A

Are scissor lifts / elevated platforms being used safely?

N/A

Are boom lifts and other aerial devices being used safely?

N/A

Is heavy equipment being used safely?

Satisfactory

Comment

Grading



Are electrical items being used safely?

Satisfactory

Are roofing operations being performed safely?

N/A

Is demolition work being done safely?

N/A

Are all other tasks being performed safely?

Satisfactory

Comment

Ricardo team working on CMU walls



## Any other items? Satisfactory

#### Comment

Installing pipes along the street

