

## **PROJECT INSPECTION**

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Pacific Hydrotech Corporation	Type of Inspection:	General Construction
Project	C2306 Drying Beds SB	Date of Inspection	August 21, 2024
Inspector Name	Ricardo Vanzzini	Time of Inspection	10:40 AM

NOTES						
19	11	<b>0</b>	<b>8</b>			
Items Inspected	Satisfactory	Unsatisfactory	N/A			

Work on site consist of continued permanent fall protection, installation, and concrete patchwork.

# **INSPECTION ITEMS**

General	
Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	Satisfactory
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	Satisfactory
Is drinking water and shade set up sufficient for the amount of workers?	Satisfactory
Are emergency and labor law postings in place?	Satisfactory
Comment	

Emergency and labor law postings are properly displayed on site.

Satisfactory

### Is Personal Protective Equipment being worn as required? Comment

All required PPE is being worn by every employee on site.

#### Are scaffolding safety procedures being followed?

#### Are hand and power tools being used safely?

#### Is good housekeeping being maintained?

#### Comment

Good housekeeping is being maintained throughout the site.

Is fall protection in place where required?



Satisfactory

### Satisfactory

Satisfactory



Comment

N/A

Permanent fall protection is being properly installed throughout the site.



Is trenching & excavation work being done safely?	N/A
Are confined space safety procedures being followed?	N/A
Are scissor lifts / elevated platforms being used safely?	N/A
Are boom lifts and other aerial devices being used safely?	N/A
Is heavy equipment being used safely?	N/A
Are electrical items being used safely?	Satisfactory
Are roofing operations being performed safely?	N/A
Is demolition work being done safely?	N/A
Are all other tasks being performed safely?	Satisfactory