

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Pacific Hydrotech Corporation	Type of Inspection:	General Construction
Project	C2307 Well 208	Date of Inspection	September 05, 2024
Inspector Name	Ricardo Vanzzini	Time of Inspection	11:18 AM

NOTES						
19	7	0	12			
Items Inspected	Satisfactory	Unsatisfactory	N/A			

Work on site has been temporarily suspended.

INSPECTION ITEMS

General	
Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	Satisfactory
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	Satisfactory
Is drinking water and shade set up sufficient for the amount of workers?	Satisfactory
Are emergency and labor law postings in place?	Satisfactory
Is Personal Protective Equipment being worn as required?	N/A
Are scaffolding safety procedures being followed?	N/A
Are hand and power tools being used safely?	N/A
Is good housekeeping being maintained?	Satisfactory

Comment

Good housekeeping is being maintained throughout the site.



Is fall protection in place where required?	N/A
Is trenching & excavation work being done safely?	N/A
Are confined space safety procedures being followed?	N/A
Are scissor lifts / elevated platforms being used safely?	N/A
Are boom lifts and other aerial devices being used safely?	N/A
Is heavy equipment being used safely?	N/A
Are electrical items being used safely?	N/A
Are roofing operations being performed safely?	N/A
Is demolition work being done safely?	N/A
Are all other tasks being performed safely?	Satisfactory
Any other items?	Satisfactory