



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Pacific Hydrotech Corporation	Type of Inspection:	General Construction
Project	C2307 Well 208	Date of Inspection	September 20, 2024
Inspector Name	Frank Gomez	Time of Inspection	07:26 AM

NOTES

19 Items Inspected	11 Satisfactory	0 Unsatisfactory	8 N/A
-----------------------	--------------------	---------------------	----------

INSPECTION ITEMS

General

Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? **Satisfactory**

Comment

First aid kit on site



Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings) **Satisfactory**

Comment

Yes



Is drinking water and shade set up sufficient for the amount of workers?

Satisfactory

Comment

Yes



Are emergency and labor law postings in place?

Satisfactory

Comment

Posted



Is Personal Protective Equipment being worn as required?

Satisfactory

Are scaffolding safety procedures being followed?

N/A

Are hand and power tools being used safely?

Satisfactory

Comment

Yes



Is good housekeeping being maintained?

Satisfactory

Comment

Good housekeeping



Is fall protection in place where required?

Satisfactory

Is trenching & excavation work being done safely?

N/A

Are confined space safety procedures being followed?

N/A

Are scissor lifts / elevated platforms being used safely?

N/A

Are boom lifts and other aerial devices being used safely?

N/A

Is heavy equipment being used safely?

N/A

Are electrical items being used safely?

Satisfactory

Are roofing operations being performed safely?

N/A

Is demolition work being done safely?

N/A

Are all other tasks being performed safely?

Satisfactory

Comment

Removing concrete forms



Any other items?

Satisfactory