



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Pacific Hydrotech Corporation	Type of Inspection:	General Construction
Project	C2314 Reservoir Mgmt. Rancho	Date of Inspection	February 05, 2025
Inspector Name	Janell Gomez	Time of Inspection	08:51 AM

NOTES

19 Items Inspected	8 Satisfactory	1 Unsatisfactory	10 N/A
------------------------------	--------------------------	----------------------------	------------------

Only one PH employee on-site getting parts for other site


INSPECTION ITEMS

General

Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? **Satisfactory**

Comment

Yes fire extinguisher is on site



Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings) **Satisfactory**

Comment

Yes available on-site

-

Is drinking water and shade set up sufficient for the amount of workers? **Satisfactory**

Comment

Yes adequate water onsite -

Are emergency and labor law postings in place? **Satisfactory**

Comment

Yes labor laws are posted onsite -

Is Personal Protective Equipment being worn as required? **Satisfactory**

Are scaffolding safety procedures being followed? **N/A**

Are hand and power tools being used safely? **N/A**

Is good housekeeping being maintained? **Unsatisfactory**

Comment

Accumulation of Trash needs to be dispose properly



Is fall protection in place where required? **Satisfactory**

Is trenching & excavation work being done safely? **N/A**

Are confined space safety procedures being followed? **N/A**

Are scissor lifts / elevated platforms being used safely? **N/A**

Are boom lifts and other aerial devices being used safely? **N/A**

Is heavy equipment being used safely? **N/A**

Are electrical items being used safely?

N/A

Are roofing operations being performed safely?

N/A

Is demolition work being done safely?

N/A

Are all other tasks being performed safely?

Satisfactory

Any other items?

Satisfactory