



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Pacific Hydrotech Corporation	Type of Inspection:	General Construction
Project	C2319 RANCHO AMIGOS BONSALL	Date of Inspection	July 12, 2024
Inspector Name	Frank Gomez	Time of Inspection	11:08 AM

NOTES

19 Items Inspected	13 Satisfactory	0 Unsatisfactory	6 N/A
------------------------------	---------------------------	----------------------------	-----------------

INSPECTION ITEMS

General

Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? **Satisfactory**

Comment

Type your custom comment...



Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings) **Satisfactory**

Is drinking water and shade set up sufficient for the amount of workers? **Satisfactory**

Comment

Type your custom comment...



Are emergency and labor law postings in place?

Satisfactory

Comment

Type your custom comment...



Is Personal Protective Equipment being worn as required?

Satisfactory

Are scaffolding safety procedures being followed?

N/A

Are hand and power tools being used safely?

Satisfactory

Is good housekeeping being maintained?

Satisfactory

Comment

Dust Control



Is fall protection in place where required?

Satisfactory

Is trenching & excavation work being done safely?

Satisfactory

Are confined space safety procedures being followed?

N/A

Are scissor lifts / elevated platforms being used safely?

N/A

Are boom lifts and other aerial devices being used safely?

N/A

Is heavy equipment being used safely?

Satisfactory

Comment

Yes



Are electrical items being used safely?

Satisfactory

Are roofing operations being performed safely?

N/A

Is demolition work being done safely?

N/A

Are all other tasks being performed safely?

Satisfactory

Comment

Potholes for Edison



Any other items?

Satisfactory