



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Pacific Hydrotech Corporation	Type of Inspection:	General Construction
Project	C2319 WEST LILAC BONSALE	Date of Inspection	June 25, 2024
Inspector Name	Frank Gomez	Time of Inspection	08:37 AM

NOTES

19 Items Inspected	13 Satisfactory	0 Unsatisfactory	6 N/A
------------------------------	---------------------------	----------------------------	-----------------

INSPECTION ITEMS

General

Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? **Satisfactory**

Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings) **Satisfactory**

Is drinking water and shade set up sufficient for the amount of workers? **Satisfactory**

Comment

Yes



Are emergency and labor law postings in place? **Satisfactory**

Comment

Yes



Is Personal Protective Equipment being worn as required?

Satisfactory

Comment

Yes



Are scaffolding safety procedures being followed?

N/A

Are hand and power tools being used safely?

Satisfactory

Is good housekeeping being maintained?

Satisfactory

Comment

Yes



Is fall protection in place where required?

Satisfactory

Is trenching & excavation work being done safely?

Satisfactory

Are confined space safety procedures being followed?

N/A

Are scissor lifts / elevated platforms being used safely?

N/A

Are boom lifts and other aerial devices being used safely?

N/A

Is heavy equipment being used safely?

Satisfactory

Comment

Yes



Are electrical items being used safely?

Satisfactory

Are roofing operations being performed safely?

N/A

Is demolition work being done safely?

N/A

Are all other tasks being performed safely?

Satisfactory

Comment

Forming footings



Any other items?

Satisfactory