



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Pacific Hydrotech Corporation	Type of Inspection:	General Construction
Project	C2320 RESERVOIR # 2	Date of Inspection	September 11, 2024
Inspector Name	Frank Gomez	Time of Inspection	11:39 AM

NOTES

19 Items Inspected	11 Satisfactory	0 Unsatisfactory	8 N/A
------------------------------	---------------------------	----------------------------	-----------------

INSPECTION ITEMS

General


Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? **Satisfactory**

Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings) **Satisfactory**

Is drinking water and shade set up sufficient for the amount of workers? **Satisfactory**

Comment

Water on site



Are emergency and labor law postings in place? **Satisfactory**

Comment

Posted



Is Personal Protective Equipment being worn as required?

Satisfactory

Comment

PPE worn



Are scaffolding safety procedures being followed?

N/A

Are hand and power tools being used safely?

Satisfactory

Comment

Yes



Is good housekeeping being maintained?

Satisfactory

Comment

Yes

Is fall protection in place where required?

Satisfactory

Comment

Caution tape around working areas



Is trenching & excavation work being done safely?

N/A

Are confined space safety procedures being followed?

N/A

Are scissor lifts / elevated platforms being used safely?

N/A

Are boom lifts and other aerial devices being used safely?

N/A

Is heavy equipment being used safely?

N/A

Are electrical items being used safely?

Satisfactory

Are roofing operations being performed safely?

N/A

Is demolition work being done safely?

N/A

Are all other tasks being performed safely?

Satisfactory

Comment

Adjusting rebar



Any other items?

Satisfactory