



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Pacific Hydrotech Corporation	Type of Inspection:	General Construction
Project	C2322 Dominguez Well 300 Compton	Date of Inspection	June 17, 2024
Inspector Name	Frank Gomez	Time of Inspection	01:23 PM

NOTES

19 Items Inspected	13 Satisfactory	0 Unsatisfactory	6 N/A
-----------------------	--------------------	---------------------	----------


INSPECTION ITEMS

General

Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? **Satisfactory**

Comment

Replacement of extinguishers



Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings) **Satisfactory**

Is drinking water and shade set up sufficient for the amount of workers? **Satisfactory**

Are emergency and labor law postings in place? **Satisfactory**

Comment

Yes



Is Personal Protective Equipment being worn as required?

Satisfactory

Comment

Type your custom comment...



Are scaffolding safety procedures being followed?

N/A

Are hand and power tools being used safely?

Satisfactory

Comment

Yes



Is good housekeeping being maintained?

Satisfactory

Comment

Yes



Is fall protection in place where required?

Satisfactory

Comment

Yes



Is trenching & excavation work being done safely?

Satisfactory

Comment

Yes



Are confined space safety procedures being followed?

N/A

Are scissor lifts / elevated platforms being used safely?

N/A

Are boom lifts and other aerial devices being used safely?

N/A

Is heavy equipment being used safely?

Satisfactory

Comment

Yes



Are electrical items being used safely?

Satisfactory

Are roofing operations being performed safely?

N/A

Is demolition work being done safely?

N/A

Are all other tasks being performed safely?

Satisfactory

Any other items?

Satisfactory

Comment

Dropped off extinguishers

