

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Pacific Hydrotech Corporation	Type of Inspection:	General Constructio	n		
Project	C2404 Well's #14, #15, & #22	Date of Inspection	December 05, 2024			
Inspector Name	Janell Gomez	Time of Inspection	08:12 AM			
NOTES						
lte	19 ems Inspected	12 Satisfactory	0 Insatisfactory	7 N/A		
INSPECTION ITEMS						
General						
Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? Satisfactory						
	Comment					
Yes on-site ,						
Is safety documentation available (Written Safety Programs, SDS, Tailgate Satisfactory Meetings)						

Comment

Yes on-site



Is drinking water and shade set up sufficient for the amount of workers? Satisfactory Comment Yes adequate water on site -Are emergency and labor law postings in place? Satisfactory Comment Yes all labor posters and permits are up to date

Comment	
Yes proper PPE is being worn	

Are scaffolding safety procedures being followed?

Are hand and power tools being used safely?

Satisfactory

Is good housekeeping being maintained?	Satisfactory
Is fall protection in place where required?	Satisfactory
Comment	
Yes	-
Is trenching & excavation work being done safely?	N/A
Are confined space safety procedures being followed?	N/A
Are scissor lifts / elevated platforms being used safely?	N/A
Are boom lifts and other aerial devices being used safely?	N/A
Is heavy equipment being used safely?	Satisfactory
Comment	
Yes heavy machinery being used safely	
Are electrical items being used safely?	Satisfactory
Are roofing operations being performed safely?	N/A
Is demolition work being done safely?	N/A
Are all other tasks being performed safely?	Satisfactory
Any other items?	Satisfactory
Comment	

Yes, sub contractor (Prada) is on site , working safely

