



# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)


<b>Company</b>	Positive Electric Co.	<b>Type of Inspection:</b>	Job Progress Inspection
<b>Project</b>	Summit Fire House	<b>Date of Inspection</b>	May 22, 2024
<b>Inspector Name</b>	Connor Gregory	<b>Time of Inspection</b>	05:24 AM

## NOTES

<b>5</b> Items Inspected	<b>5</b> Satisfactory	<b>0</b> Unsatisfactory	<b>0</b> N/A
-----------------------------	--------------------------	----------------------------	-----------------

## INSPECTION ITEMS

### General

<b>Was work completed?</b>	<b>Satisfactory</b>
<b>Comment</b>	
Nick and kris are running conduit in the hose tower for lights inside the stair tower and got the roof light mounted	

<b>Was work completed?</b>	<b>Satisfactory</b>
----------------------------	---------------------

**Comment**

Tomas wired miscellaneous equipment such as exit signs, dampers and heaters on first floor



**Was work completed?**

**Satisfactory**

**Comment**

Jake and leaf are installing app bay lights



**Was work completed?**

**Satisfactory**

**Was work completed?**

**Satisfactory**