



EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Scissor lift
Project	Summit Fire House	Date of Inspection	May 23, 2024
Inspector Name	Connor Gregory	Time of Inspection	09:26 AM

NOTES

15 Items Inspected	15 Satisfactory	0 Unsatisfactory	0 N/A
-----------------------	--------------------	---------------------	----------

INSPECTION ITEMS

General

Click "Satisfactory" and enter the model # in the comments section below **Satisfactory**

Comment	
Blue scissor lift GS-3232	-

Is the owners manual in place? **Satisfactory**

Is the back up alarm or moving alarm working? **Satisfactory**

Are the guardrails in place? **Satisfactory**

Are the tires in safe condition? **Satisfactory**

Is the emergency stop button working? **Satisfactory**

Are the indicator lights working? **Satisfactory**

Does the platform extension open and close smoothly and lock into place? **Satisfactory**

Perform a platform control check. Does everything operate smoothly?

Satisfactory

Perform a ground control check. Does everything operate smoothly?

Satisfactory

Is the lift in overall good condition and the platform clean?

Satisfactory

Are the structure, pins, scissors and covers in good condition?

Satisfactory

Can you clearly see the capacity, weight and limits not the name plate or manufacturer decals?

Satisfactory

Does the horn work?

Satisfactory

Check the batteries. Is the water level sufficient?

Satisfactory

