

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
Rubik Built LLC

**PROJECT:**  
Peabody



**INSPECTION TYPE:**  
General Construction

**INSPECTOR :** MARTIN RODRIGUEZ  
**DATE :** AUGUST 22, 2024  
**CITY :** VACAVILLE  
**STATE :** CALIFORNIA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION

<b>53</b> Items Inspected	<b>34</b> Satisfactory	<b>0</b> Unsatisfactory	<b>19</b> N/A
------------------------------	---------------------------	----------------------------	------------------

Arrived on site and began my inspection. Weather conditions are sunny with clear skies and temperatures in the 70's. There is plenty of water and access to shade for workers on site. Labor postings, emergency contact list, hospital route map and all other required safety documentation is available in the project office. First aid kit is stocked and available in the project office. Fire extinguisher is charged and ready for use. All required PPE is being used and worn. Restrooms are clean and serviced regularly. Hand wash stations are full and serviced frequently.

Hand tools are being used correctly. Power tools are in good condition and being used safely. Pneumatic nailers are in good working condition and being used safely. Air compressor tanks are bled frequently. Ladders are inspected, set up correctly and secured to prevent accidental movement. Forklift is being operated safely and seatbelt is being worn. Scaffold is in good condition and planks overlap as required. Housekeeping is well maintained. Impalement hazards are protected with rebar caps. Material storage is organized and segregated as required. Stairs and hand rails are installed and in good condition. Electrical equipment is in good working condition. Electrical cords are in good condition with all insulation intact.

There were no safety issues noted during my inspection. Great work!

# INSPECTION ITEMS

Documentation	
<b>Site Contact</b>	<b>Satisfactory</b>
<b>Comment</b>	
Curtis MacGregor (Superintendent)	-
<b>Safety Program (Including IIPP)</b>	<b>Satisfactory</b>
<b>Comment</b>	
Injury Illness Prevention Program (IIPP) is available in the project office.	-
<b>Heat Illness Prevention Program</b>	<b>Satisfactory</b>
<b>Comment</b>	

Heat Illness Prevention Awareness (HIPA) program is available in the project office and in the IIPP.	-
--	---

<b>Safety Data Sheets</b>	<b>Satisfactory</b>
<b>Comment</b>	
Safety Data Sheets (SDS) are on file.	-

<b>Daily Inspections</b>	<b>Satisfactory</b>
<b>Comment</b>	
Daily inspections are being completed.	-

<b>Tailgate Meetings</b>	<b>Satisfactory</b>
<b>Comment</b>	
Tailgate safety meetings are being completed weekly.	-

<b>Sub-Contractor Meetings</b>	<b>Satisfactory</b>
<b>Comment</b>	
Contractor safety meetings are being completed.	-

<b>OSHA Permits</b>	<b>Satisfactory</b>
<b>Comment</b>	
All required permits are on file.	-

<b>Labor Law Postings</b>	<b>Satisfactory</b>
<b>Comment</b>	
Labor postings are available in the project office.	-

<b>Emergency / Other Postings</b>	<b>Satisfactory</b>
<b>Comment</b>	
Emergency contact list and hospital route map are posted and available in the project office.	-

<b>First Aid / CPR Certification</b>	<b>Satisfactory</b>
<b>Comment</b>	

First aid/CPR certifications are on file.	-
---	---

## Emergency Items

<b>Access / Egress</b>	<b>Satisfactory</b>
------------------------	---------------------

<b>Comment</b>
----------------

Access and egress points are clear from obstructions.



<b>Elevator for Hoisting Workers (if needed)</b>	<b>N/A</b>
--	------------

<b>Fire Extinguisher(s)</b>	<b>Satisfactory</b>
-----------------------------	---------------------

<b>Comment</b>
----------------

Fire extinguisher is charged and ready for use.

-

<b>First Aid Kit(s)</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Comment</b>
----------------

First aid kit is stocked and available in the project office.

-

<b>Eye Wash Station</b>	<b>Satisfactory</b>
-------------------------	---------------------


<b>Comment</b>
----------------

There is no eye wash station mounted on site, but there is a small bottle of eye wash solution available inside the first aid kit.

-

<b>Other Fire Fighting Equipment (If needed)</b>	<b>Satisfactory</b>
--	---------------------


<b>Comment</b>
----------------

<p>Fire hydrant is available on site.</p>	
---	---

**General Items**


<p><b>Restrooms</b></p>	<p><b>Satisfactory</b></p>
-------------------------	----------------------------

<p><b>Comment</b></p>	
-----------------------	--

<p>Restrooms are clean and serviced regularly.</p>	
--	--

<p><b>Hand Washing Stations</b></p>	<p><b>Satisfactory</b></p>
-------------------------------------	----------------------------

<p><b>Comment</b></p>	
-----------------------	--

<p>Hand wash stations are full and serviced frequently.</p>	
---	---

<p><b>Waste Containers</b></p>	<p><b>Satisfactory</b></p>
--------------------------------	----------------------------

<p><b>Comment</b></p>	
-----------------------	--

<p>Waste containers are available on site and located by restrooms.</p>	
---	---

<b>Potable Water</b>		<b>Satisfactory</b>
<b>Comment</b>		
<p>There is adequate amounts of drinking water on site for workers.</p>		-

<b>Shade</b>		<b>Satisfactory</b>
<b>Comment</b>		
<p>There is plenty of shade on site for all workers.</p>		-

## Tools & Equipment

<b>Power Tools</b>		<b>Satisfactory</b>
<b>Comment</b>		
<p>Power tools are in good working condition and being used safely.</p>		-

<b>Hand Tools</b>		<b>Satisfactory</b>
<b>Comment</b>		
<p>Hand tools are being used correct;y.</p>		-

<b>Powder Actuated Tools</b>		<b>N/A</b>
------------------------------	--	------------

<b>Pneumatic Nailers</b>		<b>Satisfactory</b>
<b>Comment</b>		
<p>Pneumatic nailers are in good condition.</p>		-

<b>Mobile Elevated Work Plarforms (MEWP's)</b>		<b>N/A</b>
--	--	------------

<b>Powered Industrial Trucks</b>	<b>Satisfactory</b>
<b>Comment</b>	
Forklift is being operated safely and seatbelt is being worn.	-
<b>Heavy Mobile Equipment (Excavators, Loaders, etc)</b>	<b>N/A</b>
<b>Cranes</b>	<b>N/A</b>
<b>Cylinder Storage</b>	<b>N/A</b>
<b>Ladders</b>	<b>Satisfactory</b>
<b>Comment</b>	
Ladders are inspected, set up correctly and secured to prevent accidental movement.	-
<b>Operations</b>	
<b>Personal Protective Equipment</b>	<b>Satisfactory</b>
<b>Comment</b>	
All required PPE is being worn.	-
<b>Trenching &amp; Excavation</b>	<b>N/A</b>
<b>Fall Protection</b>	<b>N/A</b>
<b>Guardrails</b>	<b>Satisfactory</b>
<b>Comment</b>	
Guardrails are installed where needed.	-
<b>Floor / Wall Openings</b>	<b>N/A</b>
<b>Supported Scaffolding</b>	<b>Satisfactory</b>
<b>Comment</b>	

<p>Scaffolding is in good condition and safe for use.</p>	
---	---

<p><b>Mobile Scaffolding</b></p>	<p><b>N/A</b></p>
----------------------------------	-------------------

<p><b>Suspended Scaffolding</b></p>	<p><b>N/A</b></p>
-------------------------------------	-------------------

<p><b>Confined Spaces</b></p>	<p><b>N/A</b></p>
-------------------------------	-------------------

<p><b>Impalement Hazards</b></p>	<p><b>Satisfactory</b></p>
----------------------------------	----------------------------

<p><b>Comment</b></p>	
-----------------------	--

<p>Impalement hazards are protected with rebar caps.</p>	<p>-</p>
--	----------

<p><b>Traffic Control</b></p>	<p><b>Satisfactory</b></p>
-------------------------------	----------------------------

<p><b>Roofing Operations</b></p>	<p><b>N/A</b></p>
----------------------------------	-------------------

<p><b>Housekeeping</b></p>	<p><b>Satisfactory</b></p>
----------------------------	----------------------------

<p><b>Comment</b></p>	
-----------------------	--

<p>Housekeeping is well maintained.</p>	<p>-</p>
---	----------

<p><b>Demolition</b></p>	<p><b>N/A</b></p>
--------------------------	-------------------

<p><b>Silica Control</b></p>	<p><b>N/A</b></p>
------------------------------	-------------------

<p><b>Rigging Operations</b></p>	<p><b>N/A</b></p>
----------------------------------	-------------------

<p><b>Hot Work</b></p>	<p><b>N/A</b></p>
------------------------	-------------------



<b>Electrical Safety</b>		<b>Satisfactory</b>
<b>Comment</b>		
Electrical equipment and cords are in good condition with all insulation intact.	-	
<b>Lockout / Tagout</b>		<b>N/A</b>
<b>Stairways, Ramps, Runways</b>		<b>Satisfactory</b>
<b>Comment</b>		
Stairways are in good control.	-	
<b>Other Items (that were observed)</b>		<b>N/A</b>