

SAFETY INSPECTION REPORT

CONDUCTED FOR:
S.C. Valley Engineering, Inc.

PROJECT:
Job 1080 Group 765A



INSPECTION TYPE:
General Construction

INSPECTOR : JEREMY CHAVEZ
DATE : AUGUST 21, 2024
CITY : NATIONAL CITY
STATE : CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected	23 Satisfactory	1 Unsatisfactory	29 N/A
------------------------------	---------------------------	----------------------------	------------------

Jobsite located on the corner of Rising Glen Way and Hayward Way.

INSPECTION ITEMS

Documentation

Site Contact **Satisfactory**

Comment

Site walked with Dan Beeson.

Safety Program (Including IIPP) **Satisfactory**


Heat Illness Prevention Program **Satisfactory**

Safety Data Sheets **Satisfactory**

Daily Inspections **Satisfactory**

Comment

Daily inspections are being performed



Tailgate Meetings **Satisfactory**

Comment

Tailgates are being conducted at least every 10 working days



Sub-Contractor Meetings

N/A

OSHA Permits

Satisfactory

Labor Law Postings

Satisfactory

Emergency / Other Postings

Satisfactory

First Aid / CPR Certification

Satisfactory

Comment

As a note, Dan's CPR certification will be expiring soon. Please ensure the certification does not lapse.



Emergency Items

Access / Egress

N/A

Elevator for Hoisting Workers (if needed)

N/A

Fire Extinguisher(s)

Satisfactory

Comment

A fire extinguisher is readily available for employees.



First Aid Kit(s)

Satisfactory

Eye Wash Station

Satisfactory

Other Fire Fighting Equipment (If needed)

N/A

General Items

Restrooms

Satisfactory

Hand Washing Stations

Satisfactory

Waste Containers

Satisfactory

Potable Water

Satisfactory

Comment

Cool potable water has been provided for employees.



Shade

Satisfactory

Tools & Equipment

Power Tools	N/A
--------------------	------------

Hand Tools	Satisfactory
-------------------	---------------------


Powder Actuated Tools	N/A
------------------------------	------------

Pneumatic Nailers	N/A
--------------------------	------------

Mobile Elevated Work Platforms (MEWP's)	N/A
--	------------

Powered Industrial Trucks	N/A
----------------------------------	------------

Heavy Mobile Equipment (Excavators, Loaders, etc)	Satisfactory
--	---------------------

Comment	
Safe work practices were observed while employees were using heavy equipment. Daily equipment inspections are documented.	

Cranes	N/A
---------------	------------

Cylinder Storage	N/A
-------------------------	------------

Ladders	N/A
----------------	------------

Operations

Personal Protective Equipment	Unsatisfactory
--------------------------------------	-----------------------

Comment

An employee has a cap under his hardhat, which does not allow a proper fit of the hardhat. The employee complied to remove his cap.



Trenching & Excavation	Satisfactory
Fall Protection	N/A
Guardrails	N/A
Floor / Wall Openings	N/A
Supported Scaffolding	N/A
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	N/A
Traffic Control	Satisfactory
Roofing Operations	N/A
Housekeeping	Satisfactory
Demolition	N/A
Silica Control	N/A

Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	N/A
Lockout / Tagout	N/A
Stairways, Ramps, Runways	N/A
Other Items (that were observed)	N/A