

SAFETY INSPECTION REPORT

CONDUCTED FOR:
S.C. Valley Engineering, Inc.

PROJECT:
Job 1080 Group 765A



INSPECTION TYPE:
General Construction

INSPECTOR : JEREMY CHAVEZ
DATE : SEPTEMBER 16, 2024
CITY : NATIONAL CITY
STATE : CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected	23 Satisfactory	1 Unsatisfactory	29 N/A
------------------------------	---------------------------	----------------------------	------------------

Jobsite located on the corner of Rising Glen Way and Hayward Way.

INSPECTION ITEMS

Documentation

Site Contact **Satisfactory**

Comment

Site walked with Dan Beeson.

Safety Program (Including IIPP) **Satisfactory**


Heat Illness Prevention Program **Satisfactory**

Safety Data Sheets **Satisfactory**

Daily Inspections **Satisfactory**

Comment


Daily inspections are being performed



Tailgate Meetings **Satisfactory**

Comment

Tailgates are being conducted at least every 10 working days



Sub-Contractor Meetings **N/A**

OSHA Permits **Satisfactory**

Labor Law Postings **Satisfactory**

Emergency / Other Postings **Satisfactory**

First Aid / CPR Certification **Satisfactory**

Emergency Items

Access / Egress **N/A**

Elevator for Hoisting Workers (if needed) **N/A**

Fire Extinguisher(s) **Satisfactory**

First Aid Kit(s) **Satisfactory**

Eye Wash Station **Satisfactory**

Other Fire Fighting Equipment (If needed) **N/A**

General Items

Restrooms **Satisfactory**

Hand Washing Stations	Satisfactory
------------------------------	---------------------

Waste Containers	Satisfactory
-------------------------	---------------------

Potable Water	Satisfactory
----------------------	---------------------

Comment	
----------------	--

Cool potable water has been provided for employees.



Shade	Satisfactory
--------------	---------------------

Tools & Equipment	
------------------------------	--

Power Tools	N/A
--------------------	------------

Hand Tools	Satisfactory
-------------------	---------------------

Powder Actuated Tools	N/A
------------------------------	------------



Pneumatic Nailers	N/A
--------------------------	------------

Mobile Elevated Work Platforms (MEWP's)	N/A
--	------------

Powered Industrial Trucks	N/A
----------------------------------	------------

Heavy Mobile Equipment (Excavators, Loaders, etc)	Unsatisfactory
--	-----------------------

Comment	
----------------	--

<p>An employee is operating a roller while not wearing a seatbelt. The employee complied to secure his seatbelt.</p>	
<p>Good job documenting equipment inspections.</p>	

<p>Cranes</p>	<p>N/A</p>
----------------------	------------


<p>Cylinder Storage</p>	<p>N/A</p>
--------------------------------	------------

<p>Ladders</p>	<p>N/A</p>
-----------------------	------------

Operations

<p>Personal Protective Equipment</p>	<p>Satisfactory</p>
---	----------------------------

Comment

<p>Employees were observed wearing the required PPE while working around heavy equipment.</p>	
---	---

<p>Trenching & Excavation</p>	<p>Satisfactory</p>
--	----------------------------

Fall Protection	N/A
Guardrails	N/A
Floor / Wall Openings	N/A
Supported Scaffolding	N/A
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	N/A
Traffic Control	Satisfactory
Roofing Operations	N/A
Housekeeping	Satisfactory
Demolition	N/A
Silica Control	N/A
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	N/A
Lockout / Tagout	N/A
Stairways, Ramps, Runways	N/A

Other Items (that were observed)	N/A
---	------------