



EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	SCC	Type of Inspection:	Concrete Saw
Project	hj	Date of Inspection	April 16, 2024
Inspector Name	Megan Alvidrez	Time of Inspection	03:09 PM

SUMMARY OF INSPECTION

12 Items Inspected	11 Satisfactory	1 Unsatisfactory	0 N/A
-----------------------	--------------------	---------------------	----------

INSPECTION ITEMS

General

Visual inspection of unit for no damage. (If damaged, unit cannot be used and must be locked and tagged out.) **Satisfactory**

Water Flow features are fully operational and working correctly. (Engineering controls are in place.) **Satisfactory**

Check Safety Trigger to ensure it is fully operational. **Satisfactory**

Check blades to ensure they are installed correctly and not damaged. **Satisfactory**

Starter grip cable is in good condition and is not tangled or showing signs of wear and tear. **Satisfactory**

Check fuel system for leaks, especially visible parts. (Do not start if there are any leaks.) **Satisfactory**

Check abrasive wheel for good condition and that it is fitted correctly. **Satisfactory**

Inspect abrasive wheel guard for tight seat. **Satisfactory**

Check spark plug is secure.

Satisfactory

Never attempt to modify the controls or safety devices.

Satisfactory

Ensure handles are clean, dry and free of oil and dirt.

Unsatisfactory

Comment

Make sure proper PPE is in place prior to making cuts: Hard Hat, Safety Glasses, Full Face Shield, Long Pants, Boots, Hearing Protection, Dust Mask, Gloves

Satisfactory

Comment

Type your custom comment...



