



EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	SCC	Type of Inspection:	Concrete Saw
Project	hj	Date of Inspection	April 16, 2024
Inspector Name	Megan Alvidrez	Time of Inspection	03:28 PM

SUMMARY OF INSPECTION


12 Items Inspected	0 Satisfactory	1 Unsatisfactory	11 N/A
-----------------------	-------------------	---------------------	-----------

INSPECTION ITEMS

General

Visual inspection of unit for no damage. (If damaged, unit cannot be used and must be locked and tagged out.) **Unsatisfactory**

Comment

	
--	---

Water Flow features are fully operational and working correctly. (Engineering controls are in place.) **N/A**

Check Safety Trigger to ensure it is fully operational. **N/A**

Comment

Type your custom comment...



Check blades to ensure they are installed correctly and not damaged.

N/A

Starter grip cable is in good condition and is not tangled or showing signs of wear and tear.

N/A

Check fuel system for leaks, especially visible parts. (Do not start if there are any leaks.)

N/A

Check abrasive wheel for good condition and that it is fitted correctly.

N/A

Inspect abrasive wheel guard for tight seat.

N/A

Check spark plug is secure.

N/A

Never attempt to modify the controls or safety devices.

N/A

Ensure handles are clean, dry and free of oil and dirt.

N/A

Make sure proper PPE is in place prior to making cuts: Hard Hat, Safety Glasses, Full Face Shield, Long Pants, Boots, Hearing Protection, Dust Mask, Gloves

N/A

