

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
Seaside Steel Inc.

**PROJECT:**  
49000 Milmont



**INSPECTION TYPE:**  
General Construction

**INSPECTOR :** JOSHUA JOHNSON  
**DATE :** JULY 15, 2024  
**CITY :** FREMONT  
**STATE :** CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION

<b>53</b> Items Inspected	<b>30</b> Satisfactory	<b>0</b> Unsatisfactory	<b>23</b> N/A
------------------------------	---------------------------	----------------------------	------------------

Today I was able to perform a site inspection at the Fremont 49000 Milmont site. Vertical rebar is being put in place.

The following good items were observed during the visit:

- + Plenty of water on site.
- + Shade in place.
- + The work site is clean and organized.
- + Fire extinguishers are being used.
- + Materials are being staged safely.
- + Good access/egress is in place.

I am happy to report that no concerns were observed during the visit.

Carlos and his team are doing an excellent job.



•• Please see additional report notations below. •••

# INSPECTION ITEMS

Documentation	
<b>Site Contact</b>	<b>Satisfactory</b>
<b>Comment</b>	
Carlos Garcia	-
<b>Safety Program (Including IIPP)</b>	
	<b>Satisfactory</b>
<b>Comment</b>	
Available electronically.	-
<b>Heat Illness Prevention Program</b>	
	<b>Satisfactory</b>

<b>Comment</b>	
Available electronically.	-

<b>Safety Data Sheets</b>		<b>Satisfactory</b>
<b>Comment</b>		
Available to workers.		-

<b>Daily Inspections</b>		<b>Satisfactory</b>
<b>Comment</b>		
Inspections are being done.		
Another example.		

<b>Tailgate Meetings</b>		<b>Satisfactory</b>
<b>Comment</b>		
Telgate meetings are being documented.		-

<b>Sub-Contractor Meetings</b>	<b>N/A</b>
--------------------------------	------------

<b>OSHA Permits</b>	<b>Satisfactory</b>
---------------------	---------------------

<b>Labor Law Postings</b>	<b>Satisfactory</b>
<b>Comment</b>	

Posted on site.	-
-----------------	---

<b>Emergency / Other Postings</b>	<b>Satisfactory</b>
-----------------------------------	---------------------

<b>Comment</b>	
----------------	--

Posted on site.	-
-----------------	---

<b>First Aid / CPR Certification</b>	<b>Satisfactory</b>
--------------------------------------	---------------------

<b>Emergency Items</b>	
------------------------	--

<b>Access / Egress</b>	<b>Satisfactory</b>
------------------------	---------------------

<b>Comment</b>	
----------------	--

Safe access and egress is in place.	-
-------------------------------------	---

<b>Elevator for Hoisting Workers (if needed)</b>	<b>N/A</b>
--	------------

<b>Fire Extinguisher(s)</b>	<b>Satisfactory</b>
-----------------------------	---------------------

<b>Comment</b>	
----------------	--

Fire extinguishers are available on site.	-
---	---

<b>First Aid Kit(s)</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Comment</b>	
----------------	--

Available in the trailer.	-
---------------------------	---

<b>Eye Wash Station</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Comment</b>	
----------------	--

Available around the site.



<b>Other Fire Fighting Equipment (If needed)</b>	<b>N/A</b>
--	------------


## General Items

<b>Restrooms</b>	<b>Satisfactory</b>
<b>Comment</b>	
Available and stocked.	-

<b>Hand Washing Stations</b>	<b>Satisfactory</b>
<b>Comment</b>	
In place on site.	-

<b>Waste Containers</b>	<b>Satisfactory</b>
<b>Comment</b>	
In place.	-

<b>Potable Water</b>	<b>Satisfactory</b>
<b>Comment</b>	
Plenty of waters available on site.	-


<b>Shade</b>	<b>Satisfactory</b>
<b>Comment</b>	
Shade is available.	



## Tools & Equipment

<b>Power Tools</b>	<b>Satisfactory</b>
<b>Comment</b>	
No concerns observed.	-

<b>Hand Tools</b>	<b>Satisfactory</b>
<b>Comment</b>	
No concerns observed.	-
<b>Powder Actuated Tools</b>	<b>N/A</b>
<b>Pneumatic Nailers</b>	<b>N/A</b>
<b>Mobile Elevated Work Platforms (MEWP's)</b>	<b>N/A</b>
<b>Powered Industrial Trucks</b>	<b>N/A</b>
<b>Heavy Mobile Equipment (Excavators, Loaders, etc)</b>	<b>N/A</b>
<b>Cranes</b>	<b>N/A</b>
<b>Cylinder Storage</b>	<b>N/A</b>
<b>Ladders</b>	<b>N/A</b>

## Operations

<b>Personal Protective Equipment</b>	<b>Satisfactory</b>
<b>Comment</b>	
Good job wearing PPE.	


<p>Reminder was given to put safety glasses on. Corrected as shown in the photo.</p>	
<p>More good examples of PPE.</p>	

<p><b>Trenching &amp; Excavation</b></p>	<p><b>Satisfactory</b></p>
<p style="text-align: center;"><b>Comment</b></p>	
<p>No concerns observed.</p>	<p style="text-align: center;">-</p>
<p><b>Fall Protection</b></p>	<p><b>N/A</b></p>
<p><b>Guardrails</b></p>	<p><b>Satisfactory</b></p>
<p><b>Floor / Wall Openings</b></p>	<p><b>N/A</b></p>
<p><b>Supported Scaffolding</b></p>	<p><b>N/A</b></p>
<p><b>Mobile Scaffolding</b></p>	<p><b>N/A</b></p>
<p><b>Suspended Scaffolding</b></p>	<p><b>N/A</b></p>
<p><b>Confined Spaces</b></p>	<p><b>N/A</b></p>
<p><b>Impalement Hazards</b></p>	<p><b>Satisfactory</b></p>

<b>Comment</b>	
No concerns observed.	-

<b>Traffic Control</b>	<b>Satisfactory</b>
<b>Comment</b>	
No concerns observed.	-

<b>Roofing Operations</b>	<b>N/A</b>
---------------------------	------------

<b>Housekeeping</b>	<b>Satisfactory</b>
<b>Comment</b>	
Good organization observed.	

<b>Demolition</b>	<b>N/A</b>
-------------------	------------

<b>Silica Control</b>	<b>N/A</b>
-----------------------	------------

<b>Rigging Operations</b>	<b>N/A</b>
---------------------------	------------

<b>Hot Work</b>	<b>N/A</b>
-----------------	------------

<b>Electrical Safety</b>	<b>Satisfactory</b>
<b>Comment</b>	
No concerns observed.	-

<b>Lockout / Tagout</b>	<b>N/A</b>
-------------------------	------------

<b>Stairways, Ramps, Runways</b>	<b>Satisfactory</b>
----------------------------------	---------------------



**Comment**

No concerns observed.

-

**Other Items (that were observed)**

**Satisfactory**

**Comment**

Safe material storage observed.

