

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
Seaside Steel Inc.

**PROJECT:**  
ACDC



**INSPECTION TYPE:**  
General Construction

**INSPECTOR :** KELLY HEROLD  
**DATE :** JULY 02, 2024  
**CITY :** ARVIN  
**STATE :** CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION

<b>53</b> Items Inspected	<b>24</b> Satisfactory	<b>0</b> Unsatisfactory	<b>29</b> N/A
------------------------------	---------------------------	----------------------------	------------------

I met Jacob and walked jobsite with him.

The Rebar crew consolidated working on one pad and was setting rebar. The crew is wearing all PPE required. In watching work, there is good communication on lifting rebar simultaneously.


The picnic table, shaded area is right next to work area. It has lots of chilled water and ice available. The crews are encouraged to break for water anytime needed.

The materials are staged close to pad. Housekeeping is good.

# INSPECTION ITEMS

## Documentation

<b>Site Contact</b>	<b>Satisfactory</b>
<b>Comment</b>	
Met with Jacob and walked jobsite.	-
<b>Safety Program (Including IIPP)</b>	<b>Satisfactory</b>
<b>Comment</b>	
The IIPP is located in the Yocom jobsite trailer.	-
<b>Heat Illness Prevention Program</b>	<b>Satisfactory</b>
<b>Comment</b>	

<p>Heat Illness program is in jobsite trailer. Proactive shade, seating and water station next to work area.</p>	
--	---

<p><b>Safety Data Sheets</b> <span style="float: right;"><b>Satisfactory</b></span></p>	
<p style="text-align: center;"><b>Comment</b></p>	
<p>Safety Data Sheets are located in Yocom jobsite trailer.</p>	<p style="text-align: center;">-</p>

<p><b>Daily Inspections</b> <span style="float: right;"><b>Satisfactory</b></span></p>	
<p style="text-align: center;"><b>Comment</b></p>	
<p>Daily inspections are being completed.</p>	<p style="text-align: center;">-</p>

<p><b>Tailgate Meetings</b> <span style="float: right;"><b>Satisfactory</b></span></p>	
<p style="text-align: center;"><b>Comment</b></p>	
<p>Safety meetings and JHAs are reviewed as required.</p>	<p style="text-align: center;">-</p>

<p><b>Sub-Contractor Meetings</b> <span style="float: right;"><b>N/A</b></span></p>	
---	--

<p><b>OSHA Permits</b> <span style="float: right;"><b>N/A</b></span></p>	
<p style="text-align: center;"><b>Comment</b></p>	
<p>Per scope of work there are no permits required.</p>	<p style="text-align: center;">-</p>

<p><b>Labor Law Postings</b> <span style="float: right;"><b>Satisfactory</b></span></p>	
<p style="text-align: center;"><b>Comment</b></p>	
<p>Labor law postings are in the GC trailer.</p>	<p style="text-align: center;">-</p>

<p><b>Emergency / Other Postings</b> <span style="float: right;"><b>Satisfactory</b></span></p>	
<p style="text-align: center;"><b>Comment</b></p>	
<p>Heat Illness program, Industrial Truck, Emergency Numbers, Clinic directions are posted in GC trailer. Heat Illness is also posted in Yocom trailer.</p>	<p style="text-align: center;">-</p>

<b>First Aid / CPR Certification</b>	<b>Satisfactory</b>
<b>Comment</b>	
First aid certs are current.	-

## Emergency Items

<b>Access / Egress</b>	<b>Satisfactory</b>
<b>Comment</b>	
Access to jobsite is easy, no obstructions.	-

<b>Elevator for Hoisting Workers (if needed)</b>	<b>N/A</b>
--	------------

<b>Fire Extinguisher(s)</b>	<b>Satisfactory</b>
<b>Comment</b>	
Fire extinguishers are on site and available in work area.	-

<b>First Aid Kit(s)</b>	<b>Satisfactory</b>
<b>Comment</b>	
First aid kit is on site.	-

<b>Eye Wash Station</b>	<b>Satisfactory</b>
<b>Comment</b>	
Eye wash station is in work vicinity.	-

<b>Other Fire Fighting Equipment (If needed)</b>	<b>N/A</b>
--	------------

## General Items

<b>Restrooms</b>	<b>Satisfactory</b>
<b>Comment</b>	
Per crew the restrooms and hand wash stations are stocked and cleaned frequently.	-

<b>Hand Washing Stations</b>	<b>Satisfactory</b>
------------------------------	---------------------

**Comment**

Handwashing station is stocked.

-

**Waste Containers**

**Satisfactory**

**Comment**

There is a trash container on site. There is no trash seen.

-

**Potable Water**

**Satisfactory**

**Comment**

Both ice chests are full with water and ice.



**Shade**

**Satisfactory**

**Comment**

Shade available on site.



**Tools & Equipment**



**Power Tools**

**N/A**

**Hand Tools**

**Satisfactory**

**Comment**

<p>Type your custom comment...</p>	
<p>The crew is debar and tying in.</p>	

<p><b>Powder Actuated Tools</b></p>	<p>N/A</p>
-------------------------------------	------------

<p><b>Pneumatic Nailers</b></p>	<p>N/A</p>
---------------------------------	------------

<p><b>Mobile Elevated Work Platforms (MEWP's)</b></p>	<p>N/A</p>
---	------------

<p><b>Powered Industrial Trucks</b></p>	<p>Satisfactory</p>
---	---------------------

<p><b>Comment</b></p>	
<p>Reachlifts on site but not in use at time of inspection.</p>	<p>-</p>

<p><b>Heavy Mobile Equipment (Excavators, Loaders, etc)</b></p>	<p>N/A</p>
---	------------

<p><b>Cranes</b></p>	<p>N/A</p>
----------------------	------------

<p><b>Comment</b></p>	
<p>Crane on site but not associated with Sea Side work area.</p>	<p>-</p>

<p><b>Cylinder Storage</b></p>	<p>N/A</p>
--------------------------------	------------

<p><b>Ladders</b></p>	<p>N/A</p>
-----------------------	------------

## Operations

**Personal Protective Equipment**

**Satisfactory**

**Comment**

Crew wearing appropriate PPE.



**Trenching & Excavation**

**N/A**

**Fall Protection**

**N/A**

**Guardrails**

**N/A**

**Floor / Wall Openings**

**N/A**

**Supported Scaffolding**

**N/A**

**Mobile Scaffolding**

**N/A**

**Suspended Scaffolding**

**N/A**

**Confined Spaces**

**N/A**

**Impalement Hazards**

**Satisfactory**

**Comment**

Rebar is all capped. Well done on the staged rebar cage, that is capped as well.



**Traffic Control**

**N/A**

**Roofing Operations**

**N/A**

**Housekeeping**

**Satisfactory**

**Comment**

Housekeeping is good. Materials staged well. No extra materials.



I asked crew about this container and nobody knew what it was, doesn't belong to Sea Side. Looks maybe it was under a piece of heavy equipment at one time.



**Demolition**

**N/A**

**Silica Control**

**N/A**

**Rigging Operations**

**N/A**



<b>Hot Work</b>	<b>N/A</b>
-----------------	------------

<b>Comment</b>	
----------------	--

There is no hot work transpiring at this time.	-
--	---

<b>Electrical Safety</b>	<b>N/A</b>
--------------------------	------------

<b>Lockout / Tagout</b>	<b>N/A</b>
-------------------------	------------

<b>Stairways, Ramps, Runways</b>	<b>N/A</b>
----------------------------------	------------

<b>Other Items (that were observed)</b>	<b>Satisfactory</b>
---	---------------------

<b>Comment</b>	
----------------	--

<p>Crew working in unison to lift rebar.</p>	
--	--