

SAFETY INSPECTION REPORT

CONDUCTED FOR:
Seaside Steel Inc.

PROJECT:
E&P Properties



INSPECTION TYPE:
General Construction

INSPECTOR : JOSHUA JOHNSON
DATE : DECEMBER 11, 2024
CITY : GILROY
STATE : CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

54 Items Inspected	31 Satisfactory	0 Unsatisfactory	23 N/A
------------------------------	---------------------------	----------------------------	------------------

Today I was able to perform a site inspection at the Gilroy site. Rebar installation is ongoing.

The following good items were observed during the visit:

- + Good use a PPE.
- + Inspections are being documented.
- + Shade is in place.
- + Fire extinguishers are being used.
- + Water is available.
- + Power tools found with required PPE.

No concerns were found during the visit.

Carlos and his team are doing an excellent job.

ooo Please see additional report notations below. ooo

INSPECTION ITEMS

Documentation	
Site Contact	Satisfactory
Comment	
Carlos Molina	-
Safety Program (Including IIPP)	Satisfactory
Comment	
Available electronically.	-
Heat Illness Prevention Program	Satisfactory
Comment	

Available on site.	-
--------------------	---

Safety Data Sheets	Satisfactory
---------------------------	---------------------


Comment	
----------------	--

Available to all workers.	-
---------------------------	---

Daily Inspections	Satisfactory
--------------------------	---------------------

Comment	
----------------	--

Being performed and documented.



Tailgate Meetings	Satisfactory
--------------------------	---------------------

Comment	
----------------	--

Not available during the visit. They have been turned into the superintendent.

-

Sub-Contractor Meetings	N/A
--------------------------------	------------

OSHA Permits	Satisfactory
---------------------	---------------------

Comment	
----------------	--

Available in the work trailer.

-

Labor Law Postings	Satisfactory
---------------------------	---------------------

Comment	
----------------	--

In place.

-

Emergency / Other Postings	Satisfactory
-----------------------------------	---------------------

First Aid / CPR Certification	Satisfactory
--------------------------------------	---------------------

Emergency Items

Access / Egress	Satisfactory
------------------------	---------------------

Comment

No concerns observed.	-
-----------------------	---

Elevator for Hoisting Workers (if needed)	N/A
--	------------

Fire Extinguisher(s)	Satisfactory
-----------------------------	---------------------

Comment

Available throughout the site.	-
--------------------------------	---

First Aid Kit(s)	Satisfactory
-------------------------	---------------------

Comment

Available in the work trailer.	-
--------------------------------	---

Eye Wash Station	Satisfactory
-------------------------	---------------------

Comment

Available on site.



Personnel Hoist	N/A
------------------------	------------

Other Fire Fighting Equipment (If needed)	N/A
--	------------

General Items

Restrooms	Satisfactory
------------------	---------------------

Comment

Plenty of toilets are located on site and are being kept clean and in good working order.	-
---	---

Hand Washing Stations	Satisfactory
------------------------------	---------------------

Comment	
These are in place and clean.	-

Waste Containers	Satisfactory
-------------------------	---------------------

Comment	
Available on site.	-

Potable Water	Satisfactory
----------------------	---------------------

Comment	
Provided bottled water	

Shade	Satisfactory
--------------	---------------------

Tools & Equipment	
------------------------------	--

Power Tools	Satisfactory
--------------------	---------------------

Comment	
No concerns observed.	-


Hand Tools	Satisfactory
-------------------	---------------------

Comment	
No concerns observed.	-

Powder Actuated Tools	N/A
------------------------------	------------

Pneumatic Nailers	N/A
Mobile Elevated Work Platforms (MEWP's)	N/A
Powered Industrial Trucks	N/A
Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Cranes	N/A
Cylinder Storage	N/A
Ladders	N/A

Operations

Personal Protective Equipment	Satisfactory
Comment	
No concerns observed.	

Trenching & Excavation	Satisfactory
-----------------------------------	---------------------

Fall Protection	Satisfactory
Comment	
No concerns observed.	-

Guardrails	Satisfactory
-------------------	---------------------

Floor / Wall Openings	Satisfactory
------------------------------	---------------------

Supported Scaffolding	N/A
------------------------------	------------

Mobile Scaffolding	N/A
---------------------------	------------


Suspended Scaffolding	N/A
------------------------------	------------

Confined Spaces	N/A
------------------------	------------

Impalement Hazards	Satisfactory
Comment	
Protective covers designed to cover exposed reinforced steel and other similar projections so as to prevent impalement	-

Traffic Control	Satisfactory
Comment	
No concerns observed.	-

Roofing Operations	N/A
---------------------------	------------

Housekeeping	Satisfactory
Comment	
Continue to give attention to material storage areas to make sure that they are neat and organized.	

Demolition	N/A
-------------------	------------

Silica Control	N/A
-----------------------	------------

Rigging Operations	Satisfactory
---------------------------	---------------------

Comment

Ensure spreader bar has all necessary, safety labels and they are legible.



Hot Work

N/A

Electrical Safety

Satisfactory

Comment

No concerns observed.

-

Lockout / Tagout

N/A

Stairways, Ramps, Runways

N/A

Other Items (that were observed)

N/A