

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
Seaside Steel Inc.

**PROJECT:**  
Home Depot



**INSPECTION TYPE:**  
General Construction

**INSPECTOR :** JOSHUA JOHNSON  
**DATE :** MAY 08, 2024  
**CITY :** SAN JOSE  
**STATE :** CA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION

<b>52</b> Items Inspected	<b>30</b> Satisfactory	<b>0</b> Unsatisfactory	<b>22</b> N/A
------------------------------	---------------------------	----------------------------	------------------

Today I was able to perform a site inspection at the Home Depot San Jose site. The site contact was available to discuss items of concern.

Following good items were observed during the visit:


- Good use a PPE.
- Plenty of water on site.
- Shade in place.
- Inspections are being cared for.

No items of concern were found on site.

# INSPECTION ITEMS

Documentation	
<b>Site Contact</b>	<b>Satisfactory</b>
<b>Comment</b>	
Carlos Molina	-
<b>Safety Program (Including IIPP)</b>	<b>Satisfactory</b>
<b>Heat Illness Prevention Program</b>	<b>Satisfactory</b>
<b>Safety Data Sheets</b>	<b>Satisfactory</b>
<b>Daily Inspections</b>	<b>Satisfactory</b>
<b>Comment</b>	

Inspections are being completed.



**Tailgate Meetings**

**Satisfactory**

**Comment**

Meetings are being held.

-

**Sub-Contractor Meetings**

**N/A**

**OSHA Permits**

**Satisfactory**

**Labor Law Postings**

**Satisfactory**

**Emergency / Other Postings**

**Satisfactory**

**First Aid / CPR Certification**

**Satisfactory**

**Emergency Items**

**Access / Egress**

**Satisfactory**

**Fire Extinguisher(s)**

**Satisfactory**

**First Aid Kit(s)**

**Satisfactory**

**Eye Wash Station**

**Satisfactory**

**Other Fire Fighting Equipment (If needed)**

**Satisfactory**

**General Items**

<b>Restrooms</b>	<b>Satisfactory</b>
------------------	---------------------


<b>Hand Washing Stations</b>	<b>Satisfactory</b>
------------------------------	---------------------

<b>Waste Containers</b>	<b>Satisfactory</b>
-------------------------	---------------------

<b>Potable Water</b>	<b>Satisfactory</b>
----------------------	---------------------

<b>Comment</b>	
Water is on site and available.	-

<b>Shade</b>	<b>Satisfactory</b>
--------------	---------------------

<b>Comment</b>	
Shade is up.	

## Tools & Equipment

<b>Power Tools</b>	<b>Satisfactory</b>
--------------------	---------------------

<b>Comment</b>	
No concerns observed.	-

<b>Hand Tools</b>	<b>Satisfactory</b>
-------------------	---------------------

<b>Powder Actuated Tools</b>	<b>N/A</b>
------------------------------	------------

<b>Pneumatic Nailers</b>	<b>N/A</b>
--------------------------	------------

<b>Mobile Elevated Work Platforms (MEWP's)</b>	<b>N/A</b>
--	------------

<b>Powered Industrial Trucks</b>	<b>Satisfactory</b>
----------------------------------	---------------------

Heavy Mobile Equipment (Excavators, Loaders, etc)	N/A
Cranes	N/A
Cylinder Storage	N/A
Ladders	N/A

## Operations

Personal Protective Equipment **Satisfactory**

**Comment**

Good job wearing all the necessary PPE.



Trenching & Excavation	N/A
Fall Protection	N/A
Guardrails	N/A
Floor / Wall Openings	N/A
Supported Scaffolding	N/A
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A

<b>Confined Spaces</b>	<b>N/A</b>
<b>Impalement Hazards</b>	<b>Satisfactory</b>
<b>Comment</b>	
No concerns observed.	-
<b>Traffic Control</b>	<b>Satisfactory</b>
<b>Roofing Operations</b>	<b>N/A</b>
<b>Housekeeping</b>	<b>Satisfactory</b>
<b>Demolition</b>	<b>N/A</b>
<b>Silica Control</b>	<b>N/A</b>
<b>Rigging Operations</b>	<b>Satisfactory</b>
<b>Comment</b>	
No concerns observed.	-
<b>Hot Work</b>	<b>N/A</b>
<b>Electrical Safety</b>	<b>Satisfactory</b>
<b>Lockout / Tagout</b>	<b>N/A</b>
<b>Stairways, Ramps, Runways</b>	<b>Satisfactory</b>
<b>Other Items (that were observed)</b>	<b>N/A</b>