

SAFETY INSPECTION REPORT

CONDUCTED FOR:
Seaside Steel Inc.

PROJECT:
W L Butler/ Target



INSPECTION TYPE:
General Construction

INSPECTOR: FRANCISCO ROMERO
DATE: FEBRUARY 27, 2025
CITY: BAKERSFIELD
STATE: CALIFORNIA
SITE CONTACT: ODILON RENTERIA
ADDITIONAL SITE CONTACT: N/A

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

52 Items Inspected	24 Satisfactory	1 Unsatisfactory	27 N/A
------------------------------	---------------------------	----------------------------	------------------

At my Arrival to the site, I met Mr. Renteria, We started to walk the site and I wanted to Review his truck for paperwork completeness.

I reviewed:

Safety binder

First Aid kit

Fire extinguisher (they had not been updated since 2024,,) I discussed the fire extinguisher with Mr. Renteria and he was going to get a new one from Yocom.

Emergency locations.

During the inspection, I reviewed workers for PPE ON site, (Hard hats , safety glasses and Gloves). Everything looked good with them, in addition to, I reviewed workers for lifting techniques, since they were carrying and moving rebar to the different locations.

I will provide report for their review.

INSPECTION ITEMS

Documentation

Safety Program (Including IIPP)

Satisfactory

Comment

Seaside Steel

<p>Safety Program is available</p>	
------------------------------------	---

<p>Heat Illness Prevention Program</p>	<p>Satisfactory</p>
---	----------------------------

<p>Comment</p>	<p>-</p>
-----------------------	----------


<p>Heat Illness Prevention Program is available and site specific information is completed.</p>	<p>-</p>
---	----------

<p>Safety Data Sheets</p>	<p>Satisfactory</p>
----------------------------------	----------------------------

<p>Daily Inspections</p>	<p>Satisfactory</p>
---------------------------------	----------------------------

<p>Tailgate Meetings</p>	<p>Satisfactory</p>
---------------------------------	----------------------------

<p>Comment</p>	<p>-</p>
-----------------------	----------

<p>Tailgates are being conducted at least every 10 working days</p>	
---	---

<p>Sub-Contractor Meetings</p>	<p>N/A</p>
---------------------------------------	-------------------

<p>OSHA Permits</p>	<p>Satisfactory</p>
----------------------------	----------------------------

<p>Labor Law Postings</p>	<p>N/A</p>
----------------------------------	-------------------

<p>Emergency / Other Postings</p>	<p>Satisfactory</p>
--	----------------------------


First Aid / CPR Certification	N/A
--------------------------------------	------------

Emergency Items


Access / Egress	Satisfactory
------------------------	---------------------

Elevator for Hoisting Workers (if needed)	N/A
--	------------

Fire Extinguisher(s)	Unsatisfactory
-----------------------------	-----------------------

Comment	
Fire extinguisher is not current and not up-to-date	-
	

First Aid Kit(s)	Satisfactory
-------------------------	---------------------

Comment	
First aid kit was available in the truck for his crew in case of an emergency	-
	

Eye Wash Station	Satisfactory
-------------------------	---------------------

Other Fire Fighting Equipment (If needed)	N/A
--	------------

General Items

Restrooms	Satisfactory
------------------	---------------------

Comment

-

Plenty of toilets are located on site and are being kept clean and in good working order.



Hand Washing Stations

Satisfactory

Waste Containers

Satisfactory

Potable Water

Satisfactory

Comment

-

Provided bottled water



Shade

Satisfactory

Tools & Equipment

Power Tools

Satisfactory

Hand Tools

Satisfactory

Comment

-

<p>Powers tools are UL approved</p>	
-------------------------------------	---


<p>Powder Actuated Tools</p>	<p>N/A</p>
-------------------------------------	-------------------

<p>Pneumatic Nailers</p>	<p>N/A</p>
---------------------------------	-------------------

<p>Mobile Elevated Work Platforms (MEWP's)</p>	<p>N/A</p>
---	-------------------

<p>Powered Industrial Trucks</p>	<p>Satisfactory</p>
---	----------------------------

<p>Comment</p>	<p>-</p>
-----------------------	----------

<p>Operators are certified</p>	
--------------------------------	---

<p>Heavy Mobile Equipment (Excavators, Loaders, etc)</p>	<p>N/A</p>
---	-------------------


<p>Cranes</p>	<p>N/A</p>
----------------------	-------------------

<p>Cylinder Storage</p>	<p>N/A</p>
--------------------------------	-------------------

<p>Ladders</p>	<p>N/A</p>
-----------------------	-------------------

Operations

<p>Personal Protective Equipment</p>	<p>Satisfactory</p>
---	----------------------------

Comment	-
Workers were proper PPE on site , Hard hats , safety Glasses and gloves to perform their duties	

Trenching & Excavation	N/A
-----------------------------------	------------

Fall Protection	N/A
------------------------	------------

Guardrails	N/A
-------------------	------------

Floor / Wall Openings	N/A
------------------------------	------------


Supported Scaffolding	N/A
------------------------------	------------

Mobile Scaffolding	N/A
---------------------------	------------

Suspended Scaffolding	N/A
------------------------------	------------

Confined Spaces	N/A
------------------------	------------


Impalement Hazards	Satisfactory
---------------------------	---------------------

Comment	-
Protective covers designed to cover exposed reinforced steel and other similar projections so as to prevent impalement	

Traffic Control	Satisfactory
------------------------	---------------------

Roofing Operations	N/A
---------------------------	------------

Housekeeping	Satisfactory
---------------------	---------------------

Comment		-
Housekeeping in good shape.		


Demolition	N/A
-------------------	------------

Silica Control	Satisfactory
-----------------------	---------------------

Rigging Operations	N/A
---------------------------	------------

Hot Work	N/A
-----------------	------------

Electrical Safety	Satisfactory
--------------------------	---------------------

Comment		-
Verified extension cords on site , everything looked in good condition		

Lockout / Tagout	N/A
-------------------------	------------

Stairways, Ramps, Runways	N/A
----------------------------------	------------

Other Items (that were observed)	N/A
---	------------