



EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

| | | | |
|-----------------------|-----------------|----------------------------|----------------------------|
| Company | Sebastian Corp. | Type of Inspection: | Vacuum Excavator (Mud Vac) |
| Project | KTC UG 2024 | Date of Inspection | December 19, 2024 |
| Inspector Name | Tony Zarco | Time of Inspection | 10:32 AM |

NOTES

| | | | |
|-----------------------|--------------------|---------------------|----------|
| 18 Items Inspected | 14 Satisfactory | 4 Unsatisfactory | 0 N/A |
|-----------------------|--------------------|---------------------|----------|

INSPECTION ITEMS

General

| | |
|--|---------------------|
| Click "Satisfactory" and enter the serial number in the comments below | Satisfactory |
| Comment | |
| VAC003 | - |

Is the operator's manual in place? **Satisfactory**

Are all safety decals in place and legible? **Satisfactory**


Are all safety guards and shields in place with minimal damage? **Satisfactory**

Are the engine and engine components in working order with no damage? **Satisfactory**

Are all fluids filled to the proper levels for operation? **Satisfactory**

Does the engine sound normal while running? **Satisfactory**

Are all suction hoses in good working order? Gaskets installed? **Satisfactory**

| | | |
|---|---|-----------------------|
| Are all covers and doors properly secured and latched? | | Unsatisfactory |
| Comment | | |
| Front doors are missing bolts |  | |
| | - | |

| | |
|---|---------------------|
| Are all hydraulics working properly with no leaks? | Satisfactory |
|---|---------------------|

| | |
|---|---------------------|
| Are all tanks in good condition? | Satisfactory |
|---|---------------------|

| | |
|--|---------------------|
| Is the rotary nozzle in proper working condition? | Satisfactory |
|--|---------------------|

| | |
|---|---------------------|
| Are all operator controls and gauges working properly? | Satisfactory |
|---|---------------------|

| | |
|---|---------------------|
| Are the trailer and mounting bolts free from damage? | Satisfactory |
|---|---------------------|

| | |
|--|-----------------------|
| Are the tires and wheels in good condition? | Unsatisfactory |
| Comment | |
| | - |

| | |
|---|-----------------------|
| Are the brakes and/or breakaway system working properly? | Unsatisfactory |
| Comment | |
| | - |

| | |
|---|---------------------|
| Are the safety chains and hooks in good condition with minimal damage? | Satisfactory |
|---|---------------------|

| | |
|--------------------------------------|-----------------------|
| Other items not listed above? | Unsatisfactory |
| Comment | |
| | - |

