



EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Sebastian Corp.	Type of Inspection:	HDD Rig (Bore Rig)
Project	KTC UG 2024	Date of Inspection	January 02, 2025
Inspector Name	Amador Bautista	Time of Inspection	06:49 AM

NOTES

19 Items Inspected	17 Satisfactory	0 Unsatisfactory	2 N/A
------------------------------	---------------------------	----------------------------	-----------------

Vermeer

INSPECTION ITEMS

General

Click "Satisfactory" and enter the serial number in the comments below	Satisfactory
Is the operator's manual in place?	Satisfactory
Is the drill frame straight and aligned with no cracks or damage?	Satisfactory
Are the tracks and rollers in good condition and tensioned properly?	Satisfactory
Are the bearings and idlers in good condition with minimal wear?	Satisfactory
Are the pins and drive sprockets in good condition with minimal wear?	Satisfactory
Are all hydraulics working properly with no leaks?	Satisfactory

Are the rack and pinion meshed and aligned properly with minimal wear?	N/A
Is the drill pipe loading system in good condition and working properly?	Satisfactory
Is the drill pipe in good condition with minimal wear?	Satisfactory
Are the anchoring system and stabilizers in good condition with minimal excessive movement?	Satisfactory
Are the beacon housing, bits and backreamers in good condition and work properly?	Satisfactory
Are the engine and engine components in working order with no damage?	Satisfactory
Are all fluids filled to the proper levels for operation?	Satisfactory
Does the engine sound normal while running?	Satisfactory
Are all the equipment pumps working properly?	Satisfactory
Are all the operator switches and levers working properly?	Satisfactory
Do all the gauges and lights work properly?	Satisfactory
Other items not listed above?	N/A

