

## **EQUIPMENT INSPECTION**

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

	12	11	0	1	
NOTES					
	/ illiador Badilota	Inspection	00.00 / IWI		
Inspector Name	Amador Bautista	Time of	06:56 AM		
Project	KTC UG 2024	Date of Inspection	January 02, 2025		
Company	Sebastian Corp.	Type of Inspection:	Reel Trailer		

Satisfactory

Unsatisfactory

N/A

Yellow trailer

Items Inspected

## **INSPECTION ITEMS** General Are the trailer and mounting bolts free from damage? **Satisfactory** Do all the lights operate correctly? **Satisfactory** Are the tires and wheels in good condition? **Satisfactory** Is the landing gear and hitch receiver in good condition? Satisfactory Are the brakes and/or breakaway system working properly? **Satisfactory** Are the safety chains and hooks in good condition with minimal damage? **Satisfactory** Is the reel support frame in good condition? **Satisfactory** Are there any broken or damaged welds? **Satisfactory**

Are there any missing parts?	Satisfactory
Is the proper reel bar in place and in good working order?	Satisfactory
Are all safety mechanisms intact and working properly?	Satisfactory
Other items not listed above?	N/A