

EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

18 Items Inspected		16 Satisfactory	0 Unsatisfactory	2 N/A	
NOTES					
Inspector Name	Amador Bautista	Time of Inspection	12:48 PM		
Project	Middle Mile Broadband	Date of Inspection	January 17, 2025		
Company	Sebastian Corp.	Inspection:	Vacuum Excavato	r (Mud Vac)	

Vac 003

INSPECTION ITEMS General Click "Satisfactory" and enter the serial number in the comments below **Satisfactory** N/A Is the operator's manual in place? Are all safety decals in place and legible? **Satisfactory** Are all safety guards and shields in place with minimal damage? **Satisfactory** Are the engine and engine components in working order with no damage? Satisfactory Are all fluids filled to the proper levels for operation? Satisfactory Does the engine sound normal while running? **Satisfactory**

Satisfactory

Are all suction hoses in good working order? Gaskets installed?

Are all covers and doors properly secured and latched?	Satisfactory
Are all hydraulics working properly with no leaks?	Satisfactory
Are all tanks in good condition?	Satisfactory
Is the rotary nozzle in proper working condition?	Satisfactory
Are all operator controls and gauges working properly?	Satisfactory
Are the trailer and mounting bolts free from damage?	Satisfactory
Are the tires and wheels in good condition?	Satisfactory
Are the brakes and/or breakaway system working properly?	Satisfactory
Are the safety chains and hooks in good condition with minimal damage?	Satisfactory
Other items not listed above?	N/A