



EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Sebastian Corp.	Type of Inspection:	Reel Trailer
Project	Middle Mile Broadband	Date of Inspection	February 03, 2025
Inspector Name	Amador Bautista	Time of Inspection	03:02 PM

NOTES

12 Items Inspected	11 Satisfactory	0 Unsatisfactory	1 N/A
-----------------------	--------------------	---------------------	----------

Dual dolly

INSPECTION ITEMS

General	
Are the trailer and mounting bolts free from damage?	Satisfactory
Do all the lights operate correctly?	Satisfactory
Are the tires and wheels in good condition?	Satisfactory
Is the landing gear and hitch receiver in good condition?	Satisfactory
Are the brakes and/or breakaway system working properly?	Satisfactory
Are the safety chains and hooks in good condition with minimal damage?	Satisfactory
Is the reel support frame in good condition?	Satisfactory
Are there any broken or damaged welds?	Satisfactory

Are there any missing parts?	Satisfactory
Is the proper reel bar in place and in good working order?	Satisfactory
Are all safety mechanisms intact and working properly?	Satisfactory
Other items not listed above?	N/A

