

EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

			, , , , , , , , , , , , , , , , , , , ,	,
Company	Sebastian Corp.	Type of Inspection:	Air Compressor	
Project	Middle Mile Broadband	Date of Inspection	February 06, 2025	
Inspector Name	Tony Zarco	Time of Inspection	08:56 AM	
		NOTES		
		NOTES		
lte	18 ems Inspected	17 Satisfactory	1 Unsatisfactory	0 N/A
	INS	PECTION ITE	EMS	
General				
Are the engin	Satisfactory			
	Comment			
Comp004			-	
Are all fluids filled to the proper levels for operation?				Satisfactory
Does the engine sound normal while running?				Satisfactory
Are all valves	and levers working proper	rly?		Satisfactory
	Comment			
one and have	ng a new air hose on this equip it ready in case this one break ooks like it's been in the sun to	s this one has a lot of	-	
Are the hoses and connections in good working condition?				Unsatisfactory
	Comment			
Do all the gau	iges operate correctly?			Satisfactory

Are all safety mechanisms intact and working properly?	Satisfactory
Are the doors and housing in good condition?	Satisfactory
Are the pulleys and belts in good condition?	Satisfactory
Are all moving parts safe guarded?	Satisfactory
Are the trailer and mounting bolts free from damage?	Satisfactory
Do all the lights operate correctly?	Satisfactory
Are the tires and wheels in good condition?	Satisfactory
Is the landing gear and hitch receiver in good condition?	Satisfactory
Are the brakes and/or breakaway system working properly?	Satisfactory
Are the safety chains and hooks in good condition with minimal damage?	Satisfactory
Are all safety decals in place and legible?	Satisfactory
Other items not listed above?	Satisfactory