



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Silverwood Landscape Construction Inc.	Type of Inspection:	General Construction
Project	2055 Main St.	Date of Inspection	May 10, 2024
Inspector Name	Manuel Rocha	Time of Inspection	06:57 AM

NOTES

19 Items Inspected	19 Satisfactory	0 Unsatisfactory	0 N/A
-----------------------	--------------------	---------------------	----------

INSPECTION ITEMS

General

Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	Satisfactory
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	Satisfactory
Is drinking water and shade set up sufficient for the amount of workers?	Satisfactory
Are emergency and labor law postings in place?	Satisfactory
Is Personal Protective Equipment being worn as required?	Satisfactory
Are scaffolding safety procedures being followed?	Satisfactory
Are hand and power tools being used safely?	Satisfactory
Is good housekeeping being maintained?	Satisfactory
Is fall protection in place where required?	Satisfactory

Is trenching & excavation work being done safely?

Satisfactory

Are confined space safety procedures being followed?

Satisfactory

Are scissor lifts / elevated platforms being used safely?

Satisfactory

Are boom lifts and other aerial devices being used safely?

Satisfactory

Is heavy equipment being used safely?

Satisfactory

Are electrical items being used safely?

Satisfactory

Are roofing operations being performed safely?

Satisfactory

Is demolition work being done safely?

Satisfactory

Are all other tasks being performed safely?

Satisfactory

Any other items?

Satisfactory