

SAFETY INSPECTION REPORT

CONDUCTED FOR:
Silverwood Landscape Construction, Inc.

PROJECT:
Bedford - B



INSPECTION TYPE:
General Construction

INSPECTOR : ALEX MARTINEZ
DATE : SEPTEMBER 30, 2024
CITY : CORONA
STATE : CALIFORNIA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

53 Items Inspected	22 Satisfactory	0 Unsatisfactory	31 N/A
------------------------------	---------------------------	----------------------------	------------------

The job site is only a week old. Adrian and his team were on site preparing the location. They were observed marking and planning their project as well as receiving material and equipment.

Safety meeting

The crew on site and myself had a safety meeting to discuss the GHS program. We went over the companies policies as well as the location of the safety data sheets and how to use them.

Snakes

We also had a small discussion on working carefully around snakes. There are a fair amount of snakes including rattlesnakes in the Corona hillsides. With the project just commencing in a new area the crew were cautioned before skipping any large rocks or from sticking their hands in brush. The crew mentioned they had come across a few since moving over to the B side of the Bedford project.


INSPECTION ITEMS

Documentation

Site Contact Satisfactory

Comment

Adrian Mercado was on site.




Safety Program (Including IIPP) Satisfactory

Heat Illness Prevention Program Satisfactory

Safety Data Sheets	Satisfactory
Daily Inspections	Satisfactory
Tailgate Meetings	Satisfactory
Sub-Contractor Meetings	N/A
OSHA Permits	N/A
Labor Law Postings	N/A
Emergency / Other Postings	N/A
First Aid / CPR Certification	Satisfactory

Emergency Items

Access / Egress	Satisfactory
Comment	
<p>The project is about the commence and is wide open for travel. The crews container is was being dropped off during my visit.</p>	

Elevator for Hoisting Workers (if needed)	N/A
Fire Extinguisher(s)	Satisfactory
First Aid Kit(s)	Satisfactory
Eye Wash Station	N/A

Other Fire Fighting Equipment (If needed)**N/A****General Items****Restrooms****Satisfactory****Hand Washing Stations****Satisfactory****Waste Containers****Satisfactory****Potable Water****Satisfactory****Shade****Satisfactory****Tools & Equipment****Power Tools****N/A****Hand Tools****N/A****Powder Actuated Tools****N/A****Pneumatic Nailers****N/A****Mobile Elevated Work Platforms (MEWP's)****N/A****Powered Industrial Trucks****N/A****Heavy Mobile Equipment (Excavators, Loaders, etc)****N/A****Cranes****N/A****Cylinder Storage****N/A****Ladders****N/A**

Operations

Personal Protective Equipment

Satisfactory

Comment

The crew on site had the appropriate PPE for the current phase of the project.



Trenching & Excavation

N/A

Fall Protection

N/A

Guardrails

N/A

Floor / Wall Openings

Satisfactory

Supported Scaffolding

N/A

Mobile Scaffolding

N/A

Suspended Scaffolding

N/A

Confined Spaces

N/A

Impalement Hazards

Satisfactory

Traffic Control

N/A

Roofing Operations

N/A

Housekeeping	Satisfactory
Demolition	N/A
Silica Control	Satisfactory
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	Satisfactory
Lockout / Tagout	N/A
Stairways, Ramps, Runways	Satisfactory
Other Items (that were observed)	N/A