



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Silverwood Landscape Construction Inc.	Type of Inspection:	General Construction
Project	Millennium Palm Desert	Date of Inspection	December 23, 2024
Inspector Name	Israel Avila	Time of Inspection	07:05 PM

NOTES

19 Items Inspected	0 Satisfactory	0 Unsatisfactory	19 N/A
-----------------------	-------------------	---------------------	-----------

INSPECTION ITEMS

General	
Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	N/A
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	N/A
Is drinking water and shade set up sufficient for the amount of workers?	N/A
Are emergency and labor law postings in place?	N/A
Is Personal Protective Equipment being worn as required?	N/A
Are scaffolding safety procedures being followed?	N/A
Are hand and power tools being used safely?	N/A
Is good housekeeping being maintained?	N/A
Is fall protection in place where required?	N/A

Is trenching & excavation work being done safely?	N/A
Are confined space safety procedures being followed?	N/A
Are scissor lifts / elevated platforms being used safely?	N/A
Are boom lifts and other aerial devices being used safely?	N/A
Is heavy equipment being used safely?	N/A
Are electrical items being used safely?	N/A
Are roofing operations being performed safely?	N/A
Is demolition work being done safely?	N/A
Are all other tasks being performed safely?	N/A
Any other items?	N/A