

# SAFETY INSPECTION REPORT

**CONDUCTED FOR:**  
Silverwood Landscape Construction, Inc.

**PROJECT:**  
Oleander



**INSPECTION TYPE:**  
General Construction

**INSPECTOR :** ALEX MARTINEZ  
**DATE :** AUGUST 29, 2024  
**CITY :** ONTARIO  
**STATE :** CALIFORNIA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

# SUMMARY OF INSPECTION

<b>53</b> Items Inspected	<b>25</b> Satisfactory	<b>0</b> Unsatisfactory	<b>28</b> N/A
------------------------------	---------------------------	----------------------------	------------------

## Safety Meeting

The team at the Oleander project and I had a conversation on the importance of keeping up with Housekeeping regularly, we went over how it mitigates injuries and accidents and how it overall assists in keeping things safer at the project. We also went over the GHS/Hazcom program where we discussed SDS forms, maintaining labels on containers and pictograms.


# INSPECTION ITEMS

## Documentation

**Site Contact** Satisfactory

**Comment**

Meliton was on site.



**Safety Program (Including IIPP)** Satisfactory

**Comment**

Safety documentation was available in the company truck

-


**Heat Illness Prevention Program** Satisfactory

**Safety Data Sheets** Satisfactory

**Daily Inspections** Satisfactory

<b>Tailgate Meetings</b>	<b>Satisfactory</b>
<b>Sub-Contractor Meetings</b>	<b>N/A</b>
<b>OSHA Permits</b>	<b>N/A</b>
<b>Labor Law Postings</b>	<b>N/A</b>
<b>Emergency / Other Postings</b>	<b>Satisfactory</b>
<b>First Aid / CPR Certification</b>	<b>Satisfactory</b>

## Emergency Items

<b>Access / Egress</b>	<b>Satisfactory</b>
<b>Comment</b>	
All walking routes were kept clear and safe for travel.	

<b>Elevator for Hoisting Workers (if needed)</b>	<b>N/A</b>
<b>Fire Extinguisher(s)</b>	<b>Satisfactory</b>
<b>First Aid Kit(s)</b>	<b>Satisfactory</b>
<b>Eye Wash Station</b>	<b>N/A</b>
<b>Other Fire Fighting Equipment (If needed)</b>	<b>N/A</b>

## General Items

**Restrooms** **Satisfactory**


**Hand Washing Stations** **Satisfactory**

**Waste Containers** **Satisfactory**

**Potable Water** **Satisfactory**

**Comment**

Water was available for the crew.



**Shade** **Satisfactory**


## Tools & Equipment

**Power Tools** **Satisfactory**

**Hand Tools** **Satisfactory**

**Comment**


Hand tools were in fair condition.



**Powder Actuated Tools** **N/A**

Pneumatic Nailers	N/A
Mobile Elevated Work Platforms (MEWP's)	N/A
Powered Industrial Trucks	N/A
Heavy Mobile Equipment (Excavators, Loaders, etc)	Satisfactory
Cranes	N/A
Cylinder Storage	N/A
Ladders	N/A

## Operations

Personal Protective Equipment	Satisfactory
<b>Comment</b>	
All team members were observed wearing their PPE.	

Trenching & Excavation	N/A
Fall Protection	N/A
Guardrails	N/A
Floor / Wall Openings	N/A

Supported Scaffolding	N/A
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	Satisfactory
Traffic Control	N/A
Roofing Operations	N/A
Housekeeping	Satisfactory
<b>Comment</b>	
Housekeeping was well kept up with.	-
Demolition	N/A
Silica Control	Satisfactory
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	Satisfactory
Lockout / Tagout	N/A
Stairways, Ramps, Runways	Satisfactory
Other Items (that were observed)	N/A