

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Silverwood Landscape Construction Inc.	Type of Inspection:	General Construction			
Project	resort homecoming B	Date of Inspection	May 11, 2024			
Inspector Name	Jorge Vieyra	Time of Inspection	02:14 PM			
	No) TEO				
NOTES						
lte	19 ems Inspected Sat	19 isfactory	0 Unsatisfactory	0 N/A		
INSPECTION ITEMS						
General						
Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? Satisfactory						
	Comment					
Si			-			
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings) Satisfactory						
Comment						
Si			-			
Is drinking water and shade set up sufficient for the amount of workers? Satisfactory						
	Comment					
Si			-			
Are emergen	Satisfactory					
Si			-			
Is Personal P	Satisfactory					

Comment	
Si	-
Are scaffolding safety procedures being followed?	Satisfactory
Comment	
Si	-
Are hand and power tools being used safely?	Satisfactory
Comment	
Si	-
Is good housekeeping being maintained?	Satisfactory
Comment	
Si	-
Is fall protection in place where required?	Satisfactory
Comment	
Si	-
Is trenching & excavation work being done safely?	Satisfactory
Comment	
Si	-
Are confined space safety procedures being followed?	Satisfactory
Comment	
Si	-
Are scissor lifts / elevated platforms being used safely?	Satisfactory
Comment	
Si	-
Are boom lifts and other aerial devices being used safely?	Satisfactory
Comment	
Si	-
Is heavy equipment being used safely?	Satisfactory

Comment	
Si	-
Are electrical items being used safely?	Satisfactory
Comment	
Si	-
Are roofing operations being performed safely?	Satisfactory
Comment	
Si	-
Is demolition work being done safely?	Satisfactory
Comment	
Si	-
Are all other tasks being performed safely?	Satisfactory
Comment	
Si	-
Any other items?	Satisfactory
Comment	
Todo esta bien	-