

SAFETY INSPECTION REPORT

CONDUCTED FOR:
Silverwood Landscape Construction, Inc.

PROJECT:
The Bowery



INSPECTION TYPE:
General Construction

INSPECTOR : ALEX MARTINEZ
DATE : APRIL 29, 2024
CITY : SANTA ANA
STATE : CALIFORNIA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

52
Items Inspected

26
Satisfactory

0
Unsatisfactory

26
N/A

There was a large group of crew members at the Bowery project. They were observed working together on opening excavations and installing medium sized trees around the project. Hand tools were primarily being used and were found in good condition.

Water and safety documents were available in the car.

The crew and I had a safety meeting at the end of the inspection to discuss the GHS/Hazardous communication program. It's important that the crew members are working safely around chemicals are able to identify hazards.

INSPECTION ITEMS

Documentation

Site Contact

Satisfactory

Comment

Israel Avila and Juan Cruz were present at the project.

-

Safety Program (Including IIPP)

Satisfactory

Comment

Available in the safety box which is located in all company trucks.

-

Heat Illness Prevention Program

Satisfactory

Comment

Available in the safety box which is located in all company trucks.

-

Safety Data Sheets

Satisfactory

Daily Inspections


Satisfactory

Tailgate Meetings

Satisfactory

Sub-Contractor Meetings	N/A
OSHA Permits	N/A
Labor Law Postings	Satisfactory
Emergency / Other Postings	Satisfactory
First Aid / CPR Certification	Satisfactory

Emergency Items

Access / Egress	Satisfactory
Comment	
Type your custom comment...	

Fire Extinguisher(s)	Satisfactory
Comment	
Available in the company truck.	-

First Aid Kit(s)	Satisfactory
-------------------------	---------------------

Eye Wash Station	N/A
-------------------------	------------

Other Fire Fighting Equipment (If needed)	N/A
--	------------

General Items

Restrooms	Satisfactory
------------------	---------------------

Hand Washing Stations**Satisfactory****Waste Containers****Satisfactory****Potable Water****Satisfactory****Comment**

Water was available in the company trucks.

-


Shade**Satisfactory****Comment**

Permanent structures on site provide plenty of shade.


-

Tools & Equipment**Power Tools****Satisfactory****Hand Tools****Satisfactory****Comment**

Type your custom comment...

**Powder Actuated Tools****N/A****Pneumatic Nailers****N/A****Mobile Elevated Work Platforms (MEWP's)****N/A****Powered Industrial Trucks****N/A****Heavy Mobile Equipment (Excavators, Loaders, etc)****Satisfactory**

Comment

<p>Type your custom comment...</p>	
<p>Type your custom comment...</p>	
<p>Type your custom comment...</p>	

<p>Cranes</p>	<p>N/A</p>
----------------------	-------------------

<p>Cylinder Storage</p>	<p>N/A</p>
--------------------------------	-------------------

<p>Ladders</p>	<p>N/A</p>
-----------------------	-------------------

Operations

<p>Personal Protective Equipment</p>	<p>Satisfactory</p>
---	----------------------------

Comment

All crew were observed wearing PPE



Trenching & Excavation

Satisfactory

Fall Protection

N/A

Guardrails

N/A

Floor / Wall Openings

N/A

Supported Scaffolding

N/A

Mobile Scaffolding

N/A

Suspended Scaffolding

N/A

Confined Spaces

N/A

Impalement Hazards

Satisfactory

Traffic Control

N/A

Roofing Operations

N/A

Housekeeping

Satisfactory

Demolition

N/A

Silica Control

Satisfactory

Comment	
No dust was observed airborne. Water was available to control the dust.	-
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	N/A
Lockout / Tagout	N/A
Stairways, Ramps, Runways	Satisfactory
Other Items (that were observed)	N/A