

SAFETY INSPECTION REPORT

CONDUCTED FOR:
Superior Construction, Inc.

PROJECT:
Claremont



INSPECTION TYPE:
General Construction

INSPECTOR: STEVE HARRINGTON
DATE: FEBRUARY 14, 2025
CITY: CLAREMONT
STATE: CALIFORNIA
SITE CONTACT: ERNESTO
ADDITIONAL SITE CONTACT: N/A

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION

52
Items Inspected

22
Satisfactory

2
Unsatisfactory

28
N/A

Ernesto had a small work force. Most work was being performed on the third floor. In the trailer are the 2025 labor law posters and emergency info. Daily inspection and tailgate meeting are up to date.

INSPECTION ITEMS


Documentation

Safety Program (Including IIPP)

Satisfactory


Comment

Safety Manual is on site.



Comment

Site specific safety plan is also on site and available to review




Heat Illness Prevention Program

Satisfactory

Comment

Written Heat Illness prevention plan is in place




Safety Data Sheets N/A

Daily Inspections Satisfactory

Comment


Daily inspections are up to date



Tailgate Meetings Satisfactory

Comment

Tailgate was filled out. Topic was guardrail




Sub-Contractor Meetings N/A

OSHA Permits Satisfactory

Comment

Cal OSHA Annual permit is on site and up to date




Labor Law Postings

Satisfactory

Comment

New 2025 posters have been posted up




Emergency / Other Postings

Satisfactory

Comment

Emergency contacts are posted in English and Spanish



First Aid / CPR Certification

Satisfactory

Comment

Certifications were renewed December 5th and are valid until 12/2026

-

Emergency Items

Access / Egress Satisfactory


Comment	-
Two stairs give access to all floors	-

Elevator for Hoisting Workers (if needed) N/A

Fire Extinguisher(s) Satisfactory

Comment	-
Fire extinguishers are in place	

First Aid Kit(s) Satisfactory

Comment	-
First aid kit is in place and fully stocked	

Eye Wash Station N/A

Other Fire Fighting Equipment (If needed) N/A

General Items

Restrooms **Satisfactory**

Comment

Restrooms are reasonably clean and stocked.



Hand Washing Stations **Satisfactory**

Waste Containers **N/A**

Potable Water **Satisfactory**

Comment

-

Fresh clean drinking water was on site at multiple locations



Shade **Satisfactory**

Tools & Equipment

Power Tools **Satisfactory**

Comment

-

Guards are in place as required



Hand Tools

Satisfactory

Powder Actuated Tools

N/A

Pneumatic Nailers

N/A

Mobile Elevated Work Platforms (MEWP's)

N/A

Powered Industrial Trucks

N/A

Heavy Mobile Equipment (Excavators, Loaders, etc)

N/A

Cranes

N/A

Cylinder Storage

N/A

Ladders

Satisfactory

Operations

Personal Protective Equipment

Satisfactory

Comment

-

PPE was being utilized




Trenching & Excavation	N/A
Fall Protection	N/A
Guardrails	Satisfactory
Floor / Wall Openings	Satisfactory
Supported Scaffolding	N/A
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	N/A
Traffic Control	N/A
Roofing Operations	N/A
Housekeeping	Satisfactory
Demolition	N/A
Silica Control	N/A

Rigging Operations	N/A
---------------------------	------------

Hot Work	N/A
-----------------	------------

Electrical Safety	N/A
--------------------------	------------

Comment	
<p>Please note plywood has been placed on the outside of scaffolding to create a physical barrier</p>	<p>-</p> 

Lockout / Tagout	N/A
-------------------------	------------

Stairways, Ramps, Runways	Unsatisfactory
----------------------------------	-----------------------

Comment	
<p>Staircases must be kept free of obstructions</p>	<p>-</p> 

Other Items (that were observed)	Unsatisfactory
---	-----------------------

Comment	Royal West drywall
----------------	---------------------------

Drywall stacks stored in hallways are not secured from displacement

