# SAFETY INSPECTION REPORT

## **CONDUCTED FOR:**

Superior Roofing Systems

### **PROJECT:**

Balboa Peninsula



## **INSPECTION TYPE:**

**General Construction** 

**INSPECTOR:** STEVE HARRINGTON

DATE: NOVEMBER 07, 2024 CITY: NEWPORT BEACH STATE: CALIFORNIA

Safety Compliance Company is not responsible for unsafe conditions and situations not seen during this inspection. The items listed above represent only what was seen by the Safety Compliance Company Representative at the time of the inspection. Safety Compliance Company is not responsible for any ongoing unsafe condition(s) whether seen or unseen. In addition, Safety Compliance Company does not have the authority or authorization to approve, certify, or warranty any safety equipment or safety device. This agreement also indemnifies Safety Compliance Company of any omission, gross negligence, willful misconduct related to this report. Under Federal, State and Local Law, it is the responsibility of the employer and all subcontractors to mark all hazards with appropriate signs

SUMMARY OF INSPECTION			
11 Satisfactory	<b>4</b> Unsatisfactory	<b>38</b> N/A	
	11 Satisfactory	11 4	

During my site visit the guys were not able to work due to high winds. The guys were going on lunch to try and wait out the weather. Foreman was not on site at time of visit. Abram did not have any administrative documents to review. I did consult with the guys on fall protection requirements for this specific job site. Due to height of structure fall protection is required.

INSPECTION ITEMS	
Documentation	
Site Contact	Satisfactory
Safety Program (Including IIPP)	N/A
Heat Illness Prevention Program	N/A
Safety Data Sheets	N/A
Daily Inspections	N/A
Tailgate Meetings	N/A
Sub-Contractor Meetings	N/A
OSHA Permits	N/A
Labor Law Postings	Satisfactory
Comment	
Labor law poster are available at Supeiror Roofing Systems office. Please note 2025 posters will be needed soon.	-

Emergency / Other Postings	N/A
First Aid / CPR Certification	Unsatisfactory
Comment	
Emergency Items	
Access / Egress	Satisfactory
Elevator for Hoisting Workers (if needed)	N/A
Fire Extinguisher(s)	Unsatisfactory
Comment	
First Aid Kit(s)	Unsatisfactory
Comment	
Eye Wash Station	N/A
Other Fire Fighting Equipment (If needed)	N/A
General Items	
Restrooms	N/A
Hand Washing Stations	N/A
Waste Containers	N/A
Potable Water	Satisfactory

Comment

Drinking water located up on the roof. Additional water is available in Abram truck



Shade Satisfactory

# Tools & Equipment

Power Tools Satisfactory

### Comment

Power tools were in good condition. Guards were in place



Hand Tools Satisfactory

### Comment

Hand tools were free of damage



Powder Actuated Tools N/A

Pneumatic Nailers Satisfactory

### Comment

Nail gun had springs in place as required



**Mobile Elevated Work Plarforms (MEWP's)** 

N/A

**Powered Industrial Trucks** 

N/A

**Heavy Mobile Equipment (Excavators, Loaders, etc)** 

N/A

**Cranes** 

N/A

**Cylinder Storage** 

N/A

Ladders

Satisfactory

### Comment

Manufactures labels are intact available to reference.



Operations

**Personal Protective Equipment** 

N/A

**Trenching & Excavation** 

N/A

Fall Protection	N/A
Comment	
Fall protection will be needed at this job site	-
Guardrails	N/A
Floor / Wall Openings	N/A
Supported Scaffolding	N/A
Mobile Scaffolding	N/A
Suspended Scaffolding	N/A
Confined Spaces	N/A
Impalement Hazards	N/A
Traffic Control	N/A
Roofing Operations	N/A
Housekeeping	Satisfactory
Demolition	N/A
Silica Control	N/A
Rigging Operations	N/A
Hot Work	N/A
Electrical Safety	Unsatisfactory

Outlet covers was missing



Lockout / Tagout N/A

Stairways, Ramps, Runways

**Satisfactory** 

Other Items (that were observed)

N/A